

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.G.S.	
LAND OFFICE	
OPERATOR	☒

MAR 03 1981

O. C. D.
ARTESIA, OFFICE

5a. Indicate Type of Lease State ☒ Fee ☐
5. State Oil & Gas Lease No. L-6898
7. Unit Agreement Name -
8. Farm or Lease Name West Newmill Com.
9. Well No. 1
10. Field and Pool, or Wildcat Wildcat Penn.
12. County Chaves

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.

OIL WELL ☐	GAS WELL ☒	OTHER ☐
Name of Operator Read & Stevens, Inc./		
Address of Operator P.O. Box 1518, Roswell, New Mexico 88201		
Location of Well UNIT LETTER E, 2130 FEET FROM THE North LINE AND 760 FEET FROM THE West LINE, SECTION 29 TOWNSHIP 4S RANGE 26E N.M.P.M.		

15. Elevation (Show whether DF, RT, GR, etc.)

3762.7' GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
REPAIR OR ALTER CASING ☐	OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐	OTHER Perforate & Treat ☒

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-19-81 Set CIBP @ 5725' w/ 10' cement on top of CIBP, PBTD 5715', TIH w/ pkr, & 175 jts, 2 3/8" tbg. Set pkr @ 5472' RKB. Swab tbg dry to 5200'. Perf w/ tubing gun as follows. 5618'-5624' w/ 12 holes; 5644'-5650' w/ 12 holes; 5652'-5656' w/ 8 holes. Total 32 .043 holes. SION.

1-20-81 Spot acid across perfs. Set pkr at 5472' RKB, acidize perfs w/ 1000gal. 15% spearhead acid w/ 5 gal clay stabilizer. Brokedown @ 1800psi, max 2300psi, min 1100psi, avg 1600psi @ 3 1/2 BPM, ISDP 1400 psi, 15 min 1000psi. 78 BBL load water. Swab 5 hrs. Rec. 62 BBLs, 16 BBLs to recover. Last run 1000' gas on top in fluid. 4' flare. SION.

1-21-81 TP 30; FL 1300'. No GTS. Swab down to 5465'. Swab 8 hrs. Rec. 16 BLW & 29 BFMW. SION.

1-22-81 Pressure 0psi; No GTS; swab, fluid 25' from surface, swab to seat nip. Rec. 12 BFMW. Release pkr. Set CIB @ 5520', dumped 10' cmt on top of CIBP, PBTD 5510'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

by Bruce A. Stubbs TITLE Drilling & Production Mgr DATE 3-4-81

APPROVED BY Mike Williams TITLE OIL AND GAS INSPECTION DATE MAR 06 1981

ADDITIONS OF APPROVAL, IF ANY: