

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
 NM OIL & GAS CONS. MISSION
 (Other instructions on reverse side)
 Artesia, NM 88210

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS
 (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
 Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR **Max M. Wilson**

3. ADDRESS OF OPERATOR **P. O. Drawer 1978 - Roswell, NM**

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
 At surface **330' FNL and 330' FWL - Sec. 19, T.3S, R.28E**

14. PERMIT NO. _____ 15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3,973 GR

5. LEASE DESIGNATION AND SERIAL NO.
NM 12837

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Amoco Federal

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
Wildcat San And

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 19, T.3S, R.28E

12. COUNTY OR PARISH **Chaves** 13. STATE **NM**

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) Plugging	
(Other) _____		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

7/2/82

Set CIBP @ 2250' with 25 sx on top

Cut 4 1/2" casing @ 1450'

Filled hole with 9# mud

Set 200' stub plug across stub (1350' to 1550' - 100/100')

Set 100' plug across 10 3/4" shoe @ 500' (50' / 50') - Tag

Did not set 15 sx surface plug with regulation marker. Left open to 450'. This well was given to A. L. Daugherty for a water well per instructions from your Mr. George Stewart.

RECEIVED
 APR 9 1982
 U.S. GEOLOGICAL SURVEY
 ROSWELL, NEW MEXICO

*Test & Plug
 as water well
 5-11-82*

18. I hereby certify that the foregoing is true and correct

SIGNED *Max M. Wilson* TITLE Operator DATE MAY 6 1982

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE 4/8/82

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD
W. J. ...
 MAY 6 1982
 U.S. GEOLOGICAL SURVEY
 ROSWELL, NEW MEXICO