

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO.
30005-60983

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:
Twin Lakes San Andres Unit

7. Well No. 73

8. Pool name or Wildcat
Twin Lakes; San Andres (Assoc)

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3961' KB

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☐ Other ☒ Injection

2. Name of Operator
Concho Oil & Gas Corp.

3. Address of Operator
110 W. Louisiana Ste 410; Midland, Tx 79701

4. Well Location

Unit Letter E : 1650 Feet from the NORTH line and 330 feet from the WEST line

Section 5 Township 9S Range 29E NMPM Chaves County

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐


CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Concho Oil & Gas Corp. respectfully request approval to plug & abandon the Twin Lakes San Andres Unit No. 73 according to the following procedure:

1. Notify NMOCD Artesia 24 hrs prior to commencement of procedure.
2. Set 200' plug @ 2668-2868' - TA9
3. Circ hole w/ mud 2050-2150
4. Set 100' plug @ 2080-2180'.
5. Cut csg @ 1715' & POOH. ← 100' Plug 1400' - 1500'
6. Set 100' plug @ 1665-1765'. WOC & tag. 1675'
7. Set 100' plug @ 870-970'. 800' - 900'
8. Circ cmt from 175' to surface.
9. Cut off wellhead & install dry hole marker.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terri Stathem TITLE Production Analyst DATE 10-18-01

Type or print name Terri Stathem Telephone No. 915/683-7443

(This space for State use)
APPROVED BY Wild Sep ID TITLE Wild Sep ID DATE 10-30-01
Conditions of approval, if any: Notify NMOCD 24 hrs. prior to any work done

Formerly - O'Brien L #7

API No. 30-005-60983

TOC @ SURF



May-88 Csg leak. Retainer @ 1811'. Sqz'd w/ 200 sx