	CLASSIFICATION	F A C I L I T Y	H O U R S	Q U A R T	FIELD TRIP SIPO					
					Мале (М	ike stubblefiel <b>d</b>	Date	8/2-/81	Miles 217 District II	
				E R	Time of E	Departure 8:00 a.m.	Time c	of Return <u>5</u>	:00 p.mCar No. 016599	
				H O U R S	In the space below indicate the purpose of the trip and the duties performed, listing wells or leaser visited and any action taken. Signature Mar Stuffeliel					
0	0	D	3	-	1 We <b>ll</b> .	A, 17-10-25, Umex Inc. Cannon Fee #2 Cabletool is @ 85' drilling. Operator plugged & abandoned oil well @ 450'.				
Н	0	D	1	-	1 Well	I, 26-6-25, Mesa Petr. Corp. Cottonwood Fed. #1 Checked general operations of Tom Brown rig #31.				
H	0	D	-	2	l Well	34-6-25, Yates Petr. Corp. George QJ Fed. #1 Checked general operations of L&M Rig #1.				
Н	0	D	-	2	l Well	26-5-24, Yates Petr. Corp. Curtis QR Fed. #1 Checked general operations of Larue rig #1.				
Н	0	Р	1	-	2 Wells	24-5-24, Fred Pool Drlg. Co. Corn 24 #1 & #2. Inspected prod. gas wells and tank batteries for signs, leaks, spills & disposal of water to the pit. OK				
Н :	C	Ρ	2	-	9 Wells	<pre>11, 12, 31, 35, 36-T5 &amp;6S-R24 &amp; 25E, Yates Petr. Corp. Dee St. Everette OO Fed. Grynbery LZ St. GYP MO*Fed. Kuykendall OP, McClellan MB #1 &amp; #2 &amp; Thomas LN Fed. Leases. Inspected prod. gas wells &amp; tank batteries for signs, leaks, spills &amp; disposal of water to the pit. OK.</pre>				
					-		•			
					U	ileage IC FA ther217	RFA	<b></b>	Hours UIC RFA Other 8	
-	TYPE INSPECTION PLEFCRMED					INSFECTION CLASSIFICATION			NATURE OF SPECIFIC WELL OR FACILITY INSLECTED	
F C 7 5 5 7 5	- H - P - F - F - H	ousek luggi luggi ell T (pair aterf ishap ater	eepir ng ng Cl est /Hor) low or S		U = U $R = 1$ $Cn  O = 0$ $E = -$	Underground Injection Co related to injection pro resulting from injection injection and production tests, surface injection finspections relating to Other - Inspections not Reclamation Fund indicates some form of a field (show inmediately	ntrol - Any in ject, facility into any well wells, water equipment, pl Reclamation Fu related to inj	spection of or , or well or . (SWD, 2ndry flews or presen ugging, etc.) nd Activity ection or The ion taken in th	<pre>D = Drilling P = Production I = Injection core C = Corbined prod. inj. operations S = SWD U = Underground Storage G = General Operation F = Pacility or location H = Pacility of location</pre>	