S	TAT	OF	NEW	MEXICO
IERGY	DNA	MIN	ERALS	DEPARTMENT

AGT AND WINVERSED DO		11112
we. er Corics Acctives		
DISTRIBUTION		
SANTA FE	1	
FILE		
V.S.O.S.		
LAND OFFICE		
OPERATOR	1	

OIL CONSERVATION DIMENSIC &

Form	C - 1	03		
Revis	e đ	10-	۱-	78

		Form C-103
DISTRIBUTION	P. O. BOX 2088	Revised 10-1-78
BANTA FE	SANTA FE, NEW MEXICO 87501	
FILE		5a. Indicate Type of Lense
V.3.0.3.		State Fee X
LAND OFFICE		5, State Oil & Gas Lease No.
OPERATOR		J. Oldie On to Date 2
	<u> </u>	
100 VCT 1185 7 M13	SUNDRY NOTICES AND REPORTS ON WELLS FORM FOR PROPOSALS TO FRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. SE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
(BO ACT OST TWIS	SE "APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
	AS OTHER-	
Name of Operator		8. Farm or Lease Name
• •	perating Corp.	O'Brien 'FF'
Address of Operator		9. Well No.
	2203, Roswell, New Mexico 88201	2
		10. Field and Pool, or Wildcat
. Location of Well	1000 J	Twin Lakes-San Andres Assoc.
UNIT LETTER	I 2310 FEET FROM THE South LINE AND 9901 FEET FROM	mmminim
Fast	LINE, SECTION 6 TOWNSHIP 9-S RANGE 29E NMPM.	
THE	LINE, SECTIONTOWNSHIP	
mmmm	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
		Chaves
	3944.6 GR, 3949.6 KB	
.t.	Check Appropriate Box To Indicate Nature of Notice, Report or Oth	ier Data
NO	STICE OF INTENTION TO: SUBSEQUENT	REPORT OF:
NO	TICE OF INVENTION OF	
	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK		PLUG AND ABANDONMENT
TEMPORARILY ABAHDON	COMMENCE DRILLING OPNS.	PEGG AND ABANDONMENT
FULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB X	
	OTHER Perforations & T	reatment
OTHER		
Describe Proposed of work) SEE RULE II	or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
6-20-81	Spud. Ran 3 joints 8 5/8" 20# surface casing, set in ce	ment at 125 w//5
	sacks Class 'C' & 1% calcium chloride. Pressured up 100	0# for 30 minutes
	logging no pressure decrease. Circulated 20 sacks. WOO	: 18hrs.
	2000-10 1	
6 27 21	Ran 72 joints 4 1/2" 9.5# casing, set in cement at 2880'	w/200 sacks
6-27-81	self stress & 2% calcium chloride. Pressured up 1000# f	or 30 minutes
	self stress & 2% calcium chioride. Flessured up 1000% 1	or so unidees.
	logging no pressure decrease. WOC 18 hrs.	
6 30 9 1	Perforated: 2712 12 5 13 19.5, 20, 20.5, 23.5, 24, 2	8.5, 29, 29.5,

- Perforated: 2712, 12.5, 13, 19.5, 20, 20.5, 23.5, 24, 28.5, 29, 29.5, 33, 33.5, 34, 36, 36.5, 37, 37.5, 38, 38.5. (20 shots). Ran 84 joints 2 3/8" tubing, set pkr at 2600". Acidized w/9000 gals 28%, 21 balls.
 - Change of operator name effective 7-1-81 from Stevens Oil Co.

. c. I hereby certify that the information above is type and complet	e to the best of my knowledge and belief.	
SIGNED MINISTER STATES	titus Owner	DATE 7-1-81
m////	OU AND GAS INSPECTOM	JUL 9 1981

PROVED BY //WWW W/W/M/MARINEZ