

Dr ar DD
Artesia, NM 88210

RECEIVED

Form Approved.
Budget Bureau No. 42-R1424

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

MAY 15 1982

NM 14129

C. D. INDIAN, ALLOTTEE OR TRIBE NAME

ARTESIA OFFICE

7. UNIT AGREEMENT NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other

2. NAME OF OPERATOR
Harper Oil Company,

3. ADDRESS OF OPERATOR
904 Hightower, Okla. City, Okla. 73102

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 990' FSL & 890' FWL Sec. 24-
AT TOP PROD. INTERVAL: Same 5S-27E
AT TOTAL DEPTH: Same

8. FARM OR LEASE NAME

Denton-Federal

9. WELL NO.

1

10. FIELD OR WILDCAT NAME

Wildcat *Shaw*

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

24-5S-27E

12. COUNTY OR PARISH

Chaves

13. STATE

New Mexico

14. API NO.

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

☐
☐
☒
☐
☐
☐
☐
☐
☐
☐

RECEIVED
MAY 06 1982

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWEIL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 4-6-82 Set "PN" blanking plug in WB packer @ 6850'. Spot 2 sks sand on top of packer. Perforate ABO 5240'-5480'. Total 41 holes.
- 4-7-82 Acidize ABO w/4000 gals. acid
- 4-8-82 RU Howco to frac Abo down casing.
- 4-9-82 Frac w/30,000 gals. 50# WG-11 & 10,000 gals. CO₂ containing 48,500# 20/40 & 12,500# 12/20 sand.
- 5-1-82 Abo zone is non-productive. Retrieved "PN" blanking plug. Will produce Strawn zone 6946'-6980'.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE Production Manager 5-3-82

(This space for Federal or State office use)

ACCEPTED FOR RECORD

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

MAY 10 1982

U.S. GEOLOGICAL SURVEY
ROSWEIL, NEW MEXICO

*See Instructions on Reverse Side

