Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

וייים ועד ו			
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 DISTRICT II RO DESTRICT			WELL API NO. 30-005-61061
			5 Indicate Turn of Lasca
P.O. Drawer DD, Artesia, NM 88210			STATE FEE XX
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.
SUNDRY NOT	ICES AND REPORTS ON WE	LLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			7. Lease Name or Unit Agreement Name
	HVOIR. USE "APPLICATION FOR PE :-101) FOR SUCH PROPOSALS.)	PRIVILI	
1. Type of Well:			Cowboy
WEIL KX WEIL	OTHER	V	
2. Name of Operator CIBOLA ENERGY CORPORA	AT TON		8. Well No. #1
3. Address of Operator	(1 TON		9. Pool name or Wildcat
P.O. Box 1608, Albuqu	uerque, NM 87103-1608		Wildcat
4. Well Location	N	220	N No. of
Unit Letter :330	Feet From The North	Line and 330	Feet From The West Line
Section 34	Township 11 S		NMPM Chaves County
	10. Elevation (Show whether	r DF, RKB, RT, GR, etc.)	
	3655 GL	Natura of Nation D	anant on Other Date
	Appropriate Box to Indicate		SEQUENT REPORT OF:
NOTICE OF INT	ENTION TO:	306	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. DUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CE	MENT JOB
OTHER:		OTHER:	
	L		
 Describe Proposed or Completed Open work) SEE RULE 1103. 	tions (Clearly state all pertinent details,	and give pertinent dates, incl	luding estimated date of starting any proposed
Propose to plug well	as follows:		
Cut and pull ca	sing-stabilize hole w/	mud laden fluid	d. 🐫 🐫 💮
Set 25 sak plug	from TD to 7637.		FID + 6 1295
Set 25 sak plug Set 25 sak plug	from 7000-7100 at top from 5440-5540 at top	of Misslag	
Set 25 cak plug	fnom 5000 5100 at ton	af Nha	Salty Williams Commission
Set 40 sak plug	from 2327-2427 at bas	e of 8-5/8" csa	Τασ
Set 35 sak plug	from 1460-1560 at top	of San Andres.	
	from 355-455 at top o		
Set 10 sak plug	at surface with adry	hole marker.	
	1 . 1 1 1	· 100	
* Do down lit	le work before esq	way. V	
	,		
I hereby certify that the information above is true	and complete to the best of my knowledge and b	elief.	
SIGNATURE L	Mater	me Sr. Geologist	DATE 2/1/95
l sefauod			(505) 242 2050
TYPE OR PRINT NAME DOUG 1 d S L .	Marcel 2		TELEPHONE NO. (303) 242-2030
(This space for State Use)	management made process and controls		
ORIGINAL	Signed by the Mi Gum N Supervi,		FEB 1 0 1995
APPROVED BY	TO CONTROL OF THE TOTAL	MLE	DATE

CONDITIONS OF APPROVAL, IF ANY: