Submit 3 Copies to Appropriate District Office	State of New Mexico Energy, scale and Natural Resources Department OIL CONSERVATION DIVISION P.O. Box 2088			Form C-103 Revised 1-1-89 WELL API NO.	
DISTRICT I P.O. Box 1980, Hobbs, NM 88240			ION WELL API NO		
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 DISTRICT III 1000 Rio Brazos Rd., Azzec, NM 87410			5. Indicate Ty	5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No.	
(DO NOT USE THIS FORM FOR P DIFFERENT RES	TICES AND REPORTS PROPOSALS TO DRILL OR TO SERVOIR. USE "APPLICATION I C-101) FOR SUCH PROPOS	ON WELLS DEEPEN OR PLUG BAC	K TO A 7. Lease Nam	e or Unit Agreement Name	
1. Type of Well: Oll QAS WELL WELL	OTHER		Twin La	kes San Andres Unit	
2. Name of Operator			8. Well No.	96	
3. Address of Operator		<u></u>	9. Pool same		
4. Well Location					
Unit Letter :	Feet From The	Line and	d Feet 1	rom The Line	
Section	Township	Range www.whether DF, RKB, RT, G	NMPM	County	
		whether Dr, KED, KI, G	κ, ε ι.,		
	k Appropriate Box to I	ndicate Nature of N	· ·		
NOTICE OF I	NTENTION TO:		SUBSEQUEN	REPORT OF:	
			work [
	CHANGE PLANS				
]	CASING TE]	
OTHER:					
12. Describe Proposed or Completed Op		at details and size pertinent	dates including estimated d	te of starting any managed	
work) SEE RULE 1103.		, - <i>p</i>			
7/28/89: WTH w/7-3/8					
Tagged fish Shoe was wo 7/29-8/3/89: Fishing 8/4/89: Fishing. RU	n @ 1508'. Cut dow orn out. 3 J Rotary Wireline S	m to 1509.5'.	Could not make	DC's on 2-7/8" workstrin any more hole. POH. insured top of fish	
Tagged fish Shoe was wo 7/29-8/3/89: Fishing 8/4/89: Fishing. RU was @ 1508'. 8/5-8/6/89: Fishing.	n @ 1508'. Cut dow orn out. 3 J Rotary Wireline S	m to 1509.5'. ervice. Ran fi	Could not make	any more hole. POH.	
Tagged fish Shoe was wo 7/29-8/3/89: Fishing 8/4/89: Fishing. RU was @ 1508'. 8/5-8/6/89: Fishing. 8/7/89: Fishing. Mi	n @ 1508'. Cut dow orn out. J Rotary Wireline S	m to 1509.5'. ervice. Ran fi	Could not make	any more hole. POH.	
Tagged fish Shoe was wo 7/29-8/3/89: Fishing 8/4/89: Fishing. RU was @ 1508'. 8/5-8/6/89: Fishing. Mi 8/7/89: Fishing. Mi 8/8/89: Worked stuck 8/9/89: Ran free poi WIH w/ screw w/kut rite s	a @ 1508'. Cut dow orn out. 3 J Rotary Wireline S ill shoe stuck @ 15 c tools. int indicator, back v in sub, jars, DC'	m to 1509.5'. ervice. Ran fi 645'. SD. ed off top sub s on 2-7/8" DP.	Could not make sh finder log & above stuck mil Screwed into	any more hole. POH.	
Tagged fish Shoe was wo 7/29-8/3/89: Fishing 8/4/89: Fishing. RU was @ 1508'. 8/5-8/6/89: Fishing. Mi 8/7/89: Fishing. Mi 8/8/89: Worked stuck 8/9/89: Ran free poi WIH w/ screw w/kut rite s	a @ 1508'. Cut dow orn out. B Rotary Wireline S Lill shoe stuck @ 15 k tools. Int indicator, back w in sub, jars, DC' shoe & over shot. e edge on fish.	m to 1509.5'. ervice. Ran fi 645'. SD. ed off top sub s on 2-7/8" DP. Tried to wash c	Could not make sh finder log & above stuck mil Screwed into	insured top of fish ishoe. POH w/tbg & DC's fish. POH w/fish. WIH	
Tagged fish Shoe was wo 7/29-8/3/89: Fishing 8/4/89: Fishing. RU was @ 1508'. 8/5-8/6/89: Fishing. Mi 8/7/89: Fishing. Mi 8/8/89: Worked stuck 8/9/89: Ran free poi WIH w/ screw w/kut rite s with outside	a @ 1508'. Cut dow orn out. B Rotary Wireline S Lill shoe stuck @ 15 tools. Int indicator, back w in sub, jars, DC' shoe & over shot. e edge on fish.	m to 1509.5'. ervice. Ran fi 645'. SD. ed off top sub s on 2-7/8" DP. Tried to wash c	Could not make sh finder log & above stuck mil Screwed into	insured top of fish ishoe. POH w/tbg & DC's fish. POH w/fish. WIH	
Tagged fish Shoe was wo 7/29-8/3/89: Fishing 8/4/89: Fishing. RU was @ 1508'. 8/5-8/6/89: Fishing. Mi 8/7/89: Fishing. Mi 8/8/89: Worked stuck 8/9/89: Ran free poi WIH w/ screw w/kut rite s with outside	a @ 1508'. Cut dow orn out. B Rotary Wireline S Lill shoe stuck @ 15 tools. Int indicator, back w in sub, jars, DC' shoe & over shot. e edge on fish.	m to 1509.5'. ervice. Ran fi 545'. SD. ted off top sub s on 2-7/8" DP. Tried to wash o	Could not make sh finder log & above stuck mil Screwed into	insured top of fish ishoe. POH w/tbg & DC's fish. POH w/fish. WIH shoe appears to be runn	
Tagged fish Shoe was wo 7/29-8/3/89: Fishing 8/4/89: Fishing. RU was @ 1508'. 8/5-8/6/89: Fishing. Mi 8/8/89: Worked stuck 8/9/89: Ran free poi WIH w/ screw w/kut rite s with outside I bereby certify that the information above in SCONATURE	a @ 1508'. Cut dow orn out. B Rotary Wireline S Lill shoe stuck @ 15 tools. Int indicator, back w in sub, jars, DC' shoe & over shot. e edge on fish.	m to 1509.5'. ervice. Ran fi 545'. SD. ted off top sub s on 2-7/8" DP. Tried to wash o	Could not make sh finder log & above stuck mil Screwed into	insured top of fish insured top of fish l shoe. POH w/tbg & DC's fish. POH w/fish. WIH shoe appears to be runn:	