

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease: STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Twin Lakes San Andres Unit
8. Well No. 96
9. Pool name or Wildcat
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL  GAS WELL  OTHER

2. Name of Operator

3. Address of Operator

4. Well Location  
Unit Letter \_\_\_\_\_ Feet From The \_\_\_\_\_ Line and \_\_\_\_\_ Feet From The \_\_\_\_\_ Line  
Section \_\_\_\_\_ Township \_\_\_\_\_ Range \_\_\_\_\_ NMPM \_\_\_\_\_ County \_\_\_\_\_

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/24/89 (Cont): w/6-3/8" OD over shot above washpipe. Tagged @ 800'. Washed down to 838'. Pulled 124' to get back inside 8-5/8" surface casing. SD.

7/25/89: Lowered tools to 1410' and heard something falling down hole. Lowered to 1496' and stacked out. Guide string had parted & fallen down hole. WIH w/338' 2-3/8" tubing to tag top of fish. Screwed into fish. Attempted to POH. Had 2' of free travel and then hung up. POH w/2 jts (86') 4 1/2" casing. Latched back on 2-3/8" tubing and POH w/1610' 2-3/8" guide string. The guide string had been bent over and parted @ 1610'. POH w/4 1/2" casing, washpipe & tools. SD.

7/26/89: WIH w/7-7/8" bit, 4 4-3/4" drill collars on 2-7/8" workstring. Tagged @ 430'. Circ down to 443', could not make any more hole. Circ hole clean. POH, WIH w/3-7/8" bit & DC's. Could not get below 443'. POH, SD.

7/27/89: WIH w/6-3/4" bit, 4 4-3/4" DC's on 2-7/8" workstring. Drilled down to 1508' to tag fish. POH. SD.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

TYPE OR PRINT NAME \_\_\_\_\_ TELEPHONE NO. \_\_\_\_\_

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE **DEC 12 1989**

CONDITIONS OF APPROVAL, IF ANY: