

1157
DP

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Twin Lakes San Andres Unit
8. Well No. 96
9. Pool name or Wildcat Twin Lakes - San Andres Assoc.
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3916.2' GL 3921.2' KB

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Pelto Oil Company

3. Address of Operator
500 Dallas, Suite 1800, Houston, TX 77002

4. Well Location
Unit Letter D : 330 Feet From The North Line and 330 Feet From The West Line
Section 8 Township 9S Range 29E NMPM Chaves County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3916.2' GL 3921.2' KB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/4/89: Pulled & LD rods & tbgs. SD.
5/5/89: Set CIBP w/wireline @ 2720'. SD.
5/24/89: Ran Cement Bond Log. TOC @ 2078'. Ran Vertilog (Casing Inspection Log). SD.
6/1/89: Tagged CIBP w/tbgs open ended. Spotted 35' Class "C" neat cmt on plug. POH. SD.
7/18/89: Ran free point. Tagged cement inside 4½" casing @ 2640'. Top of primary outside 4½" casing is at 2078' (Bond Log). Made chemical cut @ 1702'. SD.
7/19/89: WIH w/2-3/8" guide string. Stacked out on cmt @ 2640'. Circ hole w/gel brine. POH & LD 1702' 4½" casing. SD.
7/20/89: WIH w/7-3/8" kut-rite shoe, 6 jts 6-3/8" wash pipe on 4½" csg. Washed over 178' of stub to 1870'. Circ hole. POH. SD.
7/21/89: WIH w/7-3/8" over shot on 4½" csg. Tagged @ 400', worked down to 585'. Could not get any deeper. POH. SD.
7/24/89: WIH w/7-3/8" OD kut-rite shoe & wash pipe on 4½" casing. Washed down thru tite spot @ 400' to 700'. Circ hole clean. POH. WIH w/7-3/8" OD kut-rite shoe, wash pipe

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Linda Crossley TITLE Production Analyst DATE 11/28/89
TYPE OR PRINT NAME Linda Crossley TELEPHONE NO. 713/651-1800

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE DEC 12 1989

CONDITIONS OF APPROVAL, IF ANY: