

L CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.O.S.	
LAND OFFICE	
OPERATOR	/

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
L-6906

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - II" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
Ike Lovelady, Inc.	Pennzoil B State
3. Address of Operator	9. Well No.
P.O. Drawer 2666, Midland, Texas 79702	1
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER I, 1980 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 21 TOWNSHIP 9-S RANGE 26-E N.M.P.M.	Wildcat Abo
15. Elevation (Show whether DF, RT, CR, etc.)	12. County
	Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
FULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER Completion Operations ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1-23-82 SITP 0# Ran swab fl @ Surf. Swab 21 Blw, Tbg dry w/slight show of gas.
- 1-25-82 Spot 130 gals 15% NE acid across perms. Acidize w/2500 gals 15% NE w/80 ball sealers. Ball out to 4000#. Avg. Press. 2200# Avg. rate 3 BPM. ISIP 1400# 15 min 1250#. Back flow 10 BLW. Ran swab recover 29 BLW in 3 hrs. fl 4500' fs.
- 1-26-82 12 hr SITP 100# of Acid gas. Swab 8 hrs. Recover 7 BLW, Tbg dry w/ no show of gas. 31 BLW to recover
- 1-27-82 SIPT 100#. bled off & burn to pit. Ran swab Tbg dry. POH w/ Tbg & Pkr. Perf 25 Pf @ 4592, 94, 4603, 05, 28, 32, 34, 38, 40, & 44. RIH w/RBP, Pkr, SN, 2 3/8 Tbg. Set RBP @ 4700' & Test to 500 #. Dump 2 sks. Sand on BP. Set Pkr @ 4503; Test to 500# Ran swab recover 9 BLW & Stuck Swab in Tbg.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Paul Burrow Paul Burrow

TITLE Manager of Prod.

DATE 1-29-82

APPROVED BY M. W. Wilke
CONDITIONS OF APPROVAL, IF ANY:

TITLE OIL AND GAS INSPECTOR

DATE

FEB 9 1982