Form 3160-5 (August 1999)

## TED STATES DEPARTI.. . IT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

N.M. DI JIST 2 FORM APPROVED
OMB No. 1004-0135
Septires November 30, 2000 Artesia, NIVI 502160 e Serial No.

C15/

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an NM-14291 abandoned well. Use Form 3160-3 (APD) for such proposals. 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other Instructions on reverse side 1. Type of Well 8. Well Name and No. Oil Well X Gas Well Other Lloyd's Fed Com #1 2. Name of Operator 9. API Well No. Yates Petroleum Corporation 30-005-61081 3b. Phone No. (include area code) 3a Address 10. Field and Pool, or Exploratory Area 105 S. 4th Street - Artesia, NM 88210 505-748-1471 4. Location of Well (Footage, Sec., T.,R., M., or Survey Description) Pecos Slope Abo, South 990' FSL and 1980' FEL 11. County or Parish, State Section 11 T9S-R25E Chaves Co., NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUMISSION TYPE OF ACTION X Notice of Intent Deepen Acidize Production (Start/Resume) Water Shut-Off Alter Casing Subsequent Report Fracture Treat Reclamation Well Integrity New Construction Final Abandonment Notice Casing Repair Other Recomplete Change Plans Plug and Abandon X Temporarily Abandon Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operations results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspecition.) Yates proposes to temporarily abandon this well, to hold for future deepening. Propose to temporarily abandon as follows: Notify BLM 24 hours before commencing work. Retrieve packer set at 4049'. Retrieve RBP set at 4180'. POOH with packer, RBP and tubing. Set CIBP at 4120' capped with 35' cement. Load hole with 10 pps brine plugging mud with 25 lbs of gel per bbl. Pressure test casing to 500 psi and record chart for 30 minutes. Submit chart to the BLM. If well fails pressure test, make decision on whether to locate leaks, or plug and abandon.

Name (Printed/Typed)	Title	
Susan Herpin	Engineering Technician	
ignature (	Date	
Hidr Ulipa	7-May-02	
THIS SEACE FOR FEDE	RAL OR STATE OFFICE USE	
opproved by	Title PE	Date 5/2//02
onditions of approval, if any, are attached. Approval of this notice does not warrant or certify that	Office	
e applicant holds legal or equitable title to those rights in the subject lease which would entitle the opticant to conduct operations thereon.	RFO	

or fraudulent statements or representations as to any matter within its jurisdiction