

## OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

|  |
|--|
| 3a. Indicate Type of Lease   |
| State <input type="checkbox"/> Fee <input checked="" type="checkbox"/> |
| 3. State Oil & Gas Lease No.   |

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

|  |  |
|--|--|
| OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>  | 7. Unit Agreement Name   |
| Name of Operator<br>Stevens Operating Corporation  | 8. Farm or Lease Name<br>O'Brien "GG"                          |
| Address of Operator<br>P. O. Box 2203, Roswell, New Mexico 88201   | 9. Well No.<br>3   |
| Location of Well<br>UNIT LETTER <u>E</u> , <u>1650</u> FEET FROM THE <u>North</u> LINE AND <u>330</u> FEET FROM THE <u>West</u> LINE, SECTION <u>8</u> TOWNSHIP <u>9S</u> RANGE <u>29E</u> NMPM. | 10. Field and Pool, or Wildcat<br>Twin Lakes-San Andres Assoc. |
| 11. Elevation (Show whether DF, RT, GR, etc.)<br>3919.0 GR, 3924.0 KB  | 12. County<br>Chaves   |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

## NOTICE OF INTENTION TO:

|  |   |
|--|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>     |
| PULL OR ALTER CASING <input type="checkbox"/>  | OTHER <input type="checkbox"/>            |

## SUBSEQUENT REPORT OF:

|  |   |
|--|---|
| REMEDIAL WORK <input type="checkbox"/>                         | ALTERING CASING <input type="checkbox"/>                                    |
| COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>    | PLUG AND ABANDONMENT <input type="checkbox"/>                               |
| CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/> | OTHER <u>Perforations and Treatment</u> <input checked="" type="checkbox"/> |

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 9-11-81 Spud. Ran 3 joints 8 5/8" 20# surface casing. Set in cement at 125' with 75 sacks Class "C", 2% CaCl<sub>2</sub>. Circulate 16 sacks. WOC 18 hrs. Pressure up 1000# for 30 minutes logging no pressure decrease.
- 9-20-81 Ran 71 joints 4 1/2" 9.5# casing, set in cement at 2863' with 200 sacks self stress 3% CaCl<sub>2</sub>. WOC 18 hrs. Pressure up 1000# for 30 minutes logging no pressure decrease.
- 9-24-81 Perforate 2801.5, 02, 02.5, 05.5, 06, 06.5, 11, 11.5, 12, 13.5, 14, 15, 15.5, 16, 16.5, 22.5, 23, 23.5. Ran 86 joints 2 3/8" tubing, spot 1 1/2 bbls. 28% at 2819'. Pulled 4 joints, set packer at 2702'. Acidize with 7000 gals 28% and 50 balls.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. A. S. Gussert TITLE President DATE 10-5-81APPROVED BY W. A. S. Gussert TITLE President DATE 10-7-1981

CONDITIONS OF APPROVAL, IF ANY: