

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN WRITING DATE
(Other instructions on reverse side)

Form approved.
Bureau No. 42-R1424
LEASE DESIGNATION AND SERIAL NO

Drawer DD

Artesia, NM

8558973

615F

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR RALPH NIX		8. FARM OR LEASE NAME LILLIE FEDERAL	
3. ADDRESS OF OPERATOR P.O. Box 617, Artesia, New Mexico 88210		9. WELL NO. #7	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1650' FEL & 1980' FSL, Sec. 19, T-14S, R-28E		10. FIELD AND POOL, OR WILDCAT WILDCAT SAN ANDRES	
14. PERMIT NO.		11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA Sec. 19, T-14S, R-28E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3546' GL		12. COUNTY OR PARISH Chaves	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data


NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	
(Other) <input type="checkbox"/>		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Total depth reached: 2400'

Abandon - No oil or gas of commercial quantities encountered or tested.

1. Set 150' cement plug 1600' to 1750'
2. Set 100' cement plug 231' to 331'
3. Set 10 sacks surface plug
4. Install regulation dry hole marker



OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal Approval)

APPROVED BY

(Orig. Sgd.) ROGER A. CHAPMAN

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

OCT 19 1981

JAMES A. GILLHAM
DISTRICT SUPERVISOR

*See Instructions on Reverse Side