


GRYNBERG PETROLEUM COMPANY

5000 SOUTH QUEBEC • SUITE 500 • DENVER, COLORADO 80237 USA • PHONE 303 - 850-7490

TELEX: 45-4497 ENERGY DVR
TELECOPIER: 303 - 753-9997

June 21, 1984

Oil Conservation Division
P. O. Box 2088
Santa Fe, N.M. 87501



RE: #2 Grynberg 16 State
Sec. 16, T5S-R24E
Chaves County, N. M.

Dear Sir:

At the beginning of May, we changed pumpers for our Pecos Slope Abo Production. On the above referenced well, we found a major discrepancy as to what was reported to be in our liquids tank. Exhibit "A" shows the ending report based on the prior pumper's figures and the beginning report based on the new pumper's figures.

We have no knowledge of any stealing. Our box car seals on our tanks where we unload to any haulers have not been tampered with. Whether any was taken out of the top is mere speculation. Regardless, I am sure that we should have to file some kind of amendment to our prior reports. Please advise us as to how to best rectify this matter.

Very truly yours,

GRYNBERG PETROLEUM COMPANY

Chris C. Pennels
Drilling and Production Coordinator

CCP/rb
Enclosure
CC: Artesia District Office