

INSPECTION  
CLASSIFICATIONFACILITY  
HOURSQUARTER  
HOURS

## NEW MEXICO STATE CONVENTION COMMISSION

## FIELD TRIP REPORT

Name RAY SMITHDate 4-8-97 Miles 125 District 1Time of Departure 7:30 ATime of Return 3:00 P Car No. 07

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

OP 6

2

13-10-24 Keno J. Grossly Wilson #1  
 Pick up tag & RT tag bottom e 45'  
 Mud mixed & load hole.  
 Circulate mud & rotator tag & bit  
 but could not make any hole.  
 Visit with Tim Kurn & no lead  
 to primary concern.  
 Drill 4' down 35' of cement but  
 had no cement return to surface  
 Shut down operations to let cement  
 set. Will tag plug 4-9-97.

Tim Kurn tagged plug 4-9-97 @ 26.7 ft  
 hole with cement to surface.

Mileage

UIC \_\_\_\_\_

RFA \_\_\_\_\_

Other 125Per Diem

UIC \_\_\_\_\_

RFA \_\_\_\_\_

Other \_\_\_\_\_

Hours

UIC \_\_\_\_\_

RFA \_\_\_\_\_

Other 6 1/2TYPE INSPECTION  
PERFORMEDINSPECTION  
CLASSIFICATIONNATURE OF SPECIFIC WELL  
OR FACILITY INSPECTED

- Housekeeping
- Plugging
- Plugging Cleanup
- Well Test
- Repair/Workover
- Waterflow
- Mishap or Spill
- Water Contamination

U = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SND, Indry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)

R = Inspections relating to Reclamation Fund Activity

O = Other - Inspections not related to injection or The

- D = Drilling
- P = Production
- I = Injection
- C = Combined prod. inj. operations
- S = SND
- U = Underground Storage
- G = General Operation