
-	-		-12/	
Submit 3 Copies To Appropriate District Office	State of New Me		Gp)	Form C-103 Revised March 25, 1999
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		WELL API NO.	Revised March 25, 1999
District II 811 South First, Artesia, NM 88210	OIL CONSERVATION DIVISION		30005-61261  5. Indicate Type of/Lease	
District III 1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 8/303		STATE FEE	
<u>District IV</u> 2040 South Pacheco, Santa Fe, NM 87505			6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name: Twin Lakes San Andres Unit	
1. Type of Well: Oil Well Gas Well	Other Injection			
2. Name of Operator	Other injection		7. Well No.	00
Concho Oil & Gas Corp.  3. Address of Operator			8. Pool name or	Wildcat 99
110 W. Louisiana Ste 410; Midland, Tx 79701  4. Well Location			Twin Lakes; San	Andres (Assoc)
Unit Letter H: 1650 Feet	t from the <u>North</u> line and	990_feet from th	e <u>East</u> line	;
Section 1.2		ige 28E		aves County
10. Elevation (Show whether DR, RKB, RT, CR, etc.) 3921GR				
11. Check Appr NOTICE OF INTE PERFORM REMEDIAL WORK ☐ P			SEQUENT RE	
TEMPORARILY ABANDON   C	CHANGE PLANS	COMMENCE DRIL	LING OPNS.	PLUG AND
	MULTIPLE  COMPLETION	CASING TEST AN CEMENT JOB	D 🗆	ABANDONMENT -
OTHER:		OTHER:		
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.				
Concho Oil & Gas Corp. respectfully request approval to plug and abandon the above well according to the following procedure:				
	District 24 hours prior to commer 75'. WOC & tag.			T NE 31)
<ol> <li>Circ hole w/ mud.</li> <li>Set 100' cmt plug @ 1895-199</li> </ol>	75'. WOC & tag. 1945' : 55h			
5. Perf csg @ 1540' & set 100' c	cmt plug @ 1490-1590'.			
6. Perf csg @ 830' & set 100' cn 7. [77' Perf csg @ 12". Circ cmt fro				i and a
8. Cut off wellhead & install P&				
				Ý.
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE SIGNATURE	H TITLE	Production Analy		1-11-02
(				1-11-02
Type or print name Terri Stattlem (This space for State use)	<u>1</u>	Celephone No. 915/6	003-7443 <b>&amp;</b>	
APPPROVED BY Conditions of approval, if any:	TITLE 0	Julo &	P	DATE.
or athrough or and .			1	



Formation Tops: Yates Base of Salt

San Andres

830 1540

1945

P1: 2577, 77.5, 86.5, 87, 87.5, 90, 90.5, 91, 94.5, 95, 95.5, 2604, 04.5, 07.5, 08, 09.5, 10, 10.5, 17, 17.5, 20.5, 21 Original Perf Details: 9000 gals 28% acid

Hole Size

7.875

2710 2710

PBTD

TD

TOC - unknown

P<sub>1</sub> San Andres

P<sub>2</sub> San Andres

2577

2621