Form 3160-5 (August 1999)	UNITED STATES	TERIOR	Oil C	ons	FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000	
CLINE	BUREAU OF LAND MANAC		N.M. DI	V-Dist-	Serial No	
Do not use t	his form for proposals to o vell. Use Form 3160-3 (APD)	drill or to re-ente	r 1⁄801 W. Gr ^{als.} Artesia, N			
SUBMIT IN TI	RIPLICATE - Other instru	ctions on revers	se side	7. If Unit	or CA/Agreement, Name and/or No.	
1. Type of Well				8 Wall N	Same and No.	
Oil Well Gas Well Other Name of Operator				BEVMORE "24" FEDERAL # 3		
WESTERN RESERVES OIL COMPANY 3a. Address P.O. BOX 993		Bit Phone No. (include: @fga.code) 3b. Phone No. (include: @fga.code) 915683-5533 924E CHAVES		-9. API Well No. 30-005-61309		
MIDLAND, TEXAS 79702					nd Pool, or Exploratory Area	
 Location of Well (Footage, Sec., T., R., M., or Survey Description, 1980' FSL & 1980' FEL SEC. 13 T5S-R. 				PECOS SLOPE ABO 11. County or Parish, State CHAVES CO. NEW MEXICO		
12 CHECK A	PROPRIATE BOX(ES) TO	INDICATE NAT	URE OF NOTICE, F	L REPORT, O	R OTHER DATA	
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DAT TYPE OF SUBMISSION TYPE OF ACTION						
	Acidize	Acidize Deepen Production			Slart/Resume) 🔲 Water Shut-Off	
Notice of Intent	Alter Casing	Fracture Treat	Reclamation		Well Integrity	
Subsequent Report -	Casing Repair	 New Construction Plug and Abandon 	Recomplete	bandon	U Other	
Final Abandonment Notice		Plug Back	Water Disposal			
Attach the Bond under which t following completion of the im testing has been completed. F determined that the site is ready 1. Move in well ser	he work will be performed or provi volved operations. If the operation r inal Abandonment Notices shall be	esults in a multiple co filed only after all req	mpletion or recompletion uirements, including rec	in a new inter lamation, have	oths of all pertinent markers and zones. In reports shall be filed within 30 days rval, a Form 3160-4 shall be filed once been completed, and the operator has n well head and	
install B.O.P						
3. Pull tubing, rig up wireline unit run in hole with gague ring to 3750'±. come out of hole and rig up to run CI3P, run in hole and set CIBP at 4750)±. Rig down wireline truck and run tubing back in hole. and load hole with 2% KCl water.						
if casing holds	recorder and press release pressure re release. Clean loc	move B.O.P.	Flange up well	SI, hold L head, 1	for 30 minutes rig down well	
Accepted for record	t					
only FEB	7 2002	<u></u>	<u></u>			
N Joe T. Janica		Title	Agent	·		
Signature of Amire		E Date	02/04/02			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
DCF			Title PE.	I	Date 2/5/02	
Approved by U U U Conditions of approval, if any, are certify that the applicant holds leg which would entitle the applicant to	conduct operations thereon.	does not warrant or in the subject lease	Office RF0			
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Approving Casing integrity test Only NOT the TA Status						
Approving ca	sing integrity	, test o	nly Not	the	7A Station	

BECEINED

5005 EEB - 2 WW 8:58

BOBARETE OBBICE BOBENTI DI TEKTO MOME