

Form 3160-5
(August 1990)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

5. Lease Serial No.
NM-12441

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

BEVMORE "24" FEDERAL # 3

9. API Well No.
30-005-61309

10. Field and Pool, or Exploratory Area

PECOS SLOPE-ABO

11. County or Parish, State

CHAVES CO. NEW MEXICO

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

WESTERN RESERVES OIL COMPANY (CHRIS RENAUD 915-683-5533)

3a. Address

P.O. BOX 993 MIDLAND, TEXAS 79701

3b. Phone No. (include area code)

915-683-5533

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980' FSL & 1980' FEL SEC. 13 T5S-R24E CHAVES CO. NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input checked="" type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other _____
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsurface reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

1. Set CIBP on wireline at 3750'.
2. Rigged up to pull casing, took tension on casing and it parted at 1465'. Pulled casing.
3. Went in hole with tubing to 1580' unable to go further, BLM approved setting cement plug # 1 40 Sx. from 1580-1360', tagged plug at 1360'.
4. Set plug #2 65 Sx. from 963-850', tagged plug at 853'.
5. Set plug # 3 30 Sx. at surface.
6. Cleaned location and set dry hole marker. FRW 02/18/02

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Joe T. Janica

Title Agent

Signature

Date 02/20/02

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved
Condition
certified
which v

Accepted for record

only FEB 22 2002

Title 18
States a

It does not warrant or
is in the subject lease

Title

Date

Office

It is a crime for any person knowingly and willfully to make to any department or agency of the United States to any matter within its jurisdiction.