

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

MAR 20 1992

O. C. D.
ARTESIA OFFICE

| |
|---|
| WELL API NO. 30-005-61331 |
| 5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No. LG-563 |
| 7. Lease Name or Unit Agreement Name Smeroff NL State |
| 8. Well No. 3 |
| 9. Pool name or Wildcat Parrish G. B. |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3985.8' GR |

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

| |
|--|
| 1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER P&A |
| 2. Name of Operator YATES PETROLEUM CORPORATION |
| 3. Address of Operator 105 South 4th St., Artesia, NM 88210 |
| 4. Well Location Unit Letter D : 660 Feet From The North Line and 660 Feet From The West Line Section 2 Township 5S Range 24E NMPM Chaves County |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3985.8' GR |

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

| | |
|--|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER: <input type="checkbox"/> |

SUBSEQUENT REPORT OF:

| | |
|---|--|
| REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input checked="" type="checkbox"/> |
| CASING TEST AND CEMENT JOB <input type="checkbox"/> | OTHER: <input type="checkbox"/> |

Part ID-2
4-17-92
PJA

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-13-92. Notified Darrell Moore, NMOCD, Artesia, NM of plans to P&A. Set CIBP at 3550'. RIH w/113 jts tubing and tagged BP. Loaded hole and circulated 38 BMLF. Mixed & spotted 4 sx Class "C" with 13 BMLF. Bottom plug from 3550-3506'. Laid down 43 jts tubing. Stand back 78 jts tubing. Removed BOP. Took off wellhead. Welded on lift nipple. Latched onto 4½" and pulled out of slips @ 24 points. Removed slips. Worked casing and found free point @ 2400'. RIH w/casing & cutter & cut 4½" casing at 2321'. Picked up casing and came up 12'. Hung up. Dropped casing. Worked casing free. POOH and laid down 19 joints 4½" casing. Pipe hung up. Hooked up pump and pumped 25 bbls BW down casing. Pipe stuck @ 1511'. RIH w/tubing to 2362'. Mixed & pumped 30 sx Class "C" cement and displaced w/8 BMLF. RIH w/69 jts tubing and tag TOC @ 2185'. Witnessed by NMOCD representative. POOH and laid down 28 jts tubing. Load hole w/15 BMLF. Mixed and pumped 30 sx cement and displaced w/5.5 BMLF. POOH and stand back tubing. Close in BOP. RIH w/39 joints of tubing. Tag TOC 1212'. Witnessed by Johnny Robinson, NMOCD. Obtained approval from Mike Williams, NMOCD, to cut 4½" casing at 870' and spot combination stub and shoe plug. RIH w/jet cutter and cut casing @ 870'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

(continued on page 2)

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 3-19-92
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY [Signature] TITLE Bill Rep DATE 4/21/93
CONDITIONS OF APPROVAL, IF ANY: