

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

AUG 21 '89

WELL API NO.
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Twin Lakes San Andres Unit
8. Well No. 108
9. Pool name or Wildcat Twin Lakes San Andres Assoc.
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3921' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Petco Oil Company

3. Address of Operator

4. Well Location
Unit Letter J : 2310' Feet From The South Line and 2310' Feet From The East Line

Section 7 Township 9S Range 29E NMPM Chaves County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3921' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 7-12-89: WIH w/3-7/8" bit, 6 DC's & tbg. Tagged TOC @ 733', drilled out to 747'. Cement was not hard, SD, WOC.
- 7-13-89: Drilled cement from 747' to 826', fell out of cement. Press test @ 500 psi, good. Washed fill from 1390-1462'. Tagged cement, drilled cement to 1710'. Circ hole clean. SD.
- 7-14-89: Drilled cement 1710-2072'. Dropped out of cement. Tagged TOC plug @ 2563'. Drilled cement, CIBP and fill to 2714'. SD.
- 7-15-89: Cleaned out to 2743'. Circ clean, POH. WIH w/88 jts 2-3/8", EUE production tbg with 1 2-3/8" x 8', 1 2-3/8" x 4' subs on top of the string & 1 2-3/8" SN open-ended on btm. Hung @ 2722' GL. SD.
- 7-16-89: WIH w/2" x 1 1/2" x 10' RWBC pump on a 5/8" x 2' lift sub, 108 5/8" rods, 1 5/8" x 6', 3 5/8" x 4', 1 5/8" x 2' pony rods on top of string. Hung on beam. RDPU. Job complete.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _____ TITLE _____ DATE _____

TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WELLS
SUPERVISOR, DISTRICT I

APPROVED BY _____ TITLE _____ DATE **AUG 21 1989**

CONDITIONS OF APPROVAL, IF ANY: