

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

C/SF

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other ☐
2. NAME OF OPERATOR
Stevens Operating Corporation
3. ADDRESS OF OPERATOR
P. O. Box 2203, Roswell, New Mexico 88201
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980 FNL, 1980 FWL, Sec. 28, 7S, 26E
AT TOP PROD. INTERVAL: Same
AT TOTAL DEPTH: Same
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

- | | | |
|----------------------|--------------------------|--------------------------|
| TEST WATER SHUT-OFF | <input type="checkbox"/> | <input type="checkbox"/> |
| FRACTURE TREAT | <input type="checkbox"/> | <input type="checkbox"/> |
| SHOOT OR ACIDIZE | <input type="checkbox"/> | <input type="checkbox"/> |
| REPAIR WELL | <input type="checkbox"/> | <input type="checkbox"/> |
| PULL OR ALTER CASING | <input type="checkbox"/> | <input type="checkbox"/> |
| MULTIPLE COMPLETE | <input type="checkbox"/> | <input type="checkbox"/> |
| CHANGE ZONES | <input type="checkbox"/> | <input type="checkbox"/> |
| ABANDON* | <input type="checkbox"/> | <input type="checkbox"/> |
- (other) Commence drilling and casing

5. LEASE
NM 022584
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME
----- RECEIVED
8. FARM OR LEASE NAME
Sum Federal MAR 12 1982
9. WELL NO.
3 O. C. D.
10. FIELD OR WILDCAT NAME
Wildcat Abo ARTESIA, OFFICE
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 28, T-7-S, R-26-E
12. COUNTY OR PARISH
Chaves
13. STATE
NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3706.2 GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

2-5-82 Tex Mex Rig #4, rig up and spud.

2-7-82 Ran 22 joints 8 5/8" 24.0# surface casing. Set and cement at 900' with 300 sacks 65/35 POZ and 200 sacks Class C. Circulate 100 sacks. WOC 18 hrs. Pressure up 1000# for 30 minutes logging no pressure decrease.

2-18-82 TD 4500' at 6:00 a.m.

2-20-82 Ran 112 joints 4 1/2" 10.5# casing. Set and cement at 4500' with 325 sacks Self Stress, 2% CaCl₂. WOC 18 hrs. Pressure up 1000# for 30 minutes logging no pressure decrease.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Dr. Thompson TITLE Prod. Coordinator DATE 2-25-82

(This space for Federal or State office use)

ACCEPTED FOR RECORD
APPROVED BY CHAPMAN
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____ DATE _____

MAR 2 1982

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side

