STATE OF NEW		
MERGY AND MINERALS		
we, or corice accelve		Sam. 6. 102
DISTRIBUTION	P. O. BOX 2088	Form C-103 Revised 10-1-
SANTA FE	SANTA FE, NEW MEXICO 87501	
V.\$.G.\$.		5a. Indicate Type of Leuse
LAND OFFICE	O, C. 9.	State Fee X
OPERATOR	A make of the	5. State Oil & Gas Lease No.
<u> </u>	ARTBIA, OFFICE	
(DO NOT USE THIS	SUNDRY NOTICES AND REPORTS ON WELLS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. SE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
	.5	7. Unit Agreement Name
	CLL OTHER-	0.5-
Name of Operator		8. Farm or Lease Name
Stevens Op	erating Corporation '	O'Brien "E"
Address of Operator		9. Well No.
P. O. Box	2203, Roswell, New Mexico	8
Location of Well	. 660 FEET FROM THE South LINE AND 2310 FEET FROM	10. Field and Pool, or Wildcar Twin Lakes-San Andres Assoc.
THE West	LINE, SECTION 1 TOWNSHIP 9S RANGE 28E NMPM.	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3947.3 G., 3952.3 KB	Chaves
: b.	Check Appropriate Box To Indicate Nature of Notice, Report or Oth	^
NOT		REPORT OF:
, NO	SUBSEQUENT	REPORT OF:
PERFORM REMEDIAL WORK TIMPORARILY ABAHDON FULL OR ALTER CASING	PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPHS. X CHANGE PLANS CASING TEST AND CEMENT JQB X	ALTERING CASING PLUG AND ABANDONMENT
	OTHER	
OTHER		
	Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any propose
1-26-82	Spud at 1:00 a.m. Ran 3 joints 8 5/8" 24.0# surface carcement at 130' with 75 sacks Class C, 2% CaCl2. Circul	
	WOC 18 hrs. Pressure up 1000# for 30 minutes logging redecrease.	
2-1-82	TD 2730'. Ran 75 joints of 4 1/2" 9.5# casing. Set are 2731' with 200 sacks Self Stress. WOC 18 hrs. Pressur for 30 minutes logging no pressure decrease.	
		·
	•	

Production Coordinator

OIL AND GAS INSTRUCTOR

2-4-82

FEB 8

1982

ONDITIONS OF APPROVAL, IF ANYI