

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.O.S.	
LAND OFFICE	
OPERATOR	1

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

SEP 15 1983

O. C. D.  
ARTESIA, OFFICE

Form C-103  
Revised 10-1-78

5. Indicate Type of Lease	State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.		

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER- Dry Hole	7. Unit Agreement Name
Name of Operator McClellan Oil Corporation			8. Farm or Lease Name Finch Fee
Address of Operator P.O. Drawer 730, Roswell, NM 88202			9. Well No. 2
Location of Well UNIT LETTER <u>L</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>18</u> TOWNSHIP <u>9-S</u> RANGE <u>26-E</u> NMPM.			10. Field and Pool, or Wildcat East Bitter Lake Abo
11. Elevation (Show whether DF, RT, GR, etc.) 3694' G.L.			12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

INFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
WELL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>Test upper zone</u> <input checked="" type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 8/5/83 Ran CIBP to 3800'. Dumped 15 sacks cement on plug. Perfed 4 holes at 1950' and recemented 4- $\frac{1}{2}$ " casing with 300 sx class H with 3# sand and .3% CFR-2.
- 8/8/83 Ran CBL after 48 hours; Good bond from 1900' to 900'. Perf from 1779'-1794', 1 JSPF/ 10 holes total. Acidize with 1500 gal. 10% MCA with 1000 SCF/BBL N<sup>2</sup>. Flow back and swabbed. Swabbed dry with no show.
- 3/10/83 Set CIBP at 1400'. Dumped 15 sx cement on top of CIBP. Perf well from 1231'-1263' 14 holes. Acidized with 2000 gals. 20% NEFE. Swabbed well (no oil). Pulled packer. Ran tubing to 1220', swabbed (no oil).
- 3/12/83 Released rig. Prep to plug and abandon.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Paul Ragdele TITLE Operations Manager DATE 9/14/83

APPROVED BY Mr. Walker TITLE OIL AND GAS INSPECTOR DATE SEP 20 1983

CONDITIONS OF APPROVAL, IF ANY: