orm 9-331		UL _D STATES	SUBMIT	IN TRIPLICATE*	Form approved.	
(May 1963) CONS	. COMMISSION DEPART	MENT OF THE INTERIOR	₹ (Other	instructions on re-	BUDGET BUREAU No. 42-R1424	
Torm 9-331  (May 1963) CONS. COMMISSION DEPARTMENT OF THE INTERIOR (Other Instructions on re- NN OIL CONS. GEOLOGICAL SURVEY verse side)  Drawer DD GEOLOGICAL SURVEY verse side)					5. LEASE DESIGNATION AND SERIAL NO.	
Drawer DD	88870				NM-18970	
	• • • • • • • • • • • • • • • • • • • •	ICES AND REPORTS ON	WELLS	RECEIVED epen or plug back to	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
	use this form for	"APPLYCATION FOR F		film 10 .		
	GAS	3 MAILTONITON TON	LINE	Telusaci proposars	JUNIT AGREEMENT NAME	
		<b>SEP</b> 0.1 1983	1	<u>Bur.</u>	- White	
. NAME OF OPERAT				<del>一和05世</del> 五司的制	78. FARM OR LEASE NAME	
Read & Stevens, Inc.			1		West Haystack Federal	
. ADDRESS OF OPE		ARTESIA, OFFICE			9. WELL NO.	
P.O. Box 1518,	Roswell, NM 8	8201			2	
. LOCATION OF WELL(Report location clearly and in accordance with State				ith State	10. FIELD AND POOL, OR WILDCAT	
requirements.* See also space 17 below.)					Wildcat _ Hor	
At surface					11. SEC. T.,R.,M.,OR BLK. AND	
860' FSL & 660' FWL					SURVEY OR AREA	
A DEDMIT NO		15 CLEVATIONS /Chan		DE DT CO ata 1	Section 20-T6S-R27E	
4. PERMIT NO.		15. ELEVATIONS (Show 3907! GR	whermer	pr,Ki,GK,eic.)	12. COUNTY OR PARISH 13. STATE  Chaves New Mexico	
6.	Check Appropri		Nature	of Notice, Report, Ot	,,,	
				, ,		
	NOTICE OF INTENTIO	N TO:	SUBSEQUENT REPORT OF:			
			<del></del>		<del></del>	
TEST WATER SHU	<del></del>	L OR ALTER CASING		WATER SHUT-OFF	REPAIRING WELL	
FRACTURE TREAT	<del></del>	TIPLE COMPLETE	<b>  </b>	FRACTURE TREATME		
SHOOT OR ACIDI REPAIR WELL	<del>  </del>	NDON*	<del></del>	SHOOTING OR ACID		
(Other)	I UNA	NGE PLANS			ure Stimulate X	
(Other)			<b></b>	I '	Recompletion Report and Log form.)	
7 DESCRIBE PROPO	SED OR COMPLETED OP	FRATIONS (Clearly sta	ate ali		nd give pertinent dates, including	
					ve subsurface locations and measured	
		markers and zones pe				
8-11-83	Set CIBP @ 550	Set CIBP @ 5500' w/35' cmt. Perf 1 shot/' 4742'-4750', acidiz			w/1000gal 7 1/2% MCA acid. Form.	
		I, ISIP 500ps1, 5 mi		,	, , , , , , , , , , , , , , , , , , ,	
8-12-83 Pert 4703'-4711', 1 shot/'. Acidize w/1000 gal 7 1/2% MCA aci					, form broke @ 1300psi, treated at	
	3.8 BPM, 2200p	si, ISIP 1100psi, 5m	nin 200p	sī, 10min vac.		
0 17 07	D -1 46404 467	4.1. 4.1	10000	. 7 1 (04 101 1	5	
8-13-83	Perf 4642'-4671', 1shot/'. Acidize w/2000gal 7 1/2% MCA acid. Form broke @ 900psi, treated @ 4.8 BPM, 2000psi, ISIP 500psi, 5min 200psi, 10min 50psi, 15min vac.					
	ым, 2000ры,	131° 200ps1, 200	Jopsi, i	omini Jopsi, izmin vac	O + FD 32. K	
8-14-83	Ran 4592 61 2	3/8" tbg w/SN & blas	st islat	set # 4592 61	Post FD-83 8,000	
3 14 03	Nan 4552 0 2	oro ing wrom a bras	,, join,	361 6 4372.0 .	. 11. 6 tu	
8-16-83	Frac w/glld wt	Frac w/glld wtr & 20% $\infty_2$ , pumped 22 BPM glld wtr & 6.5 BPM $\mathrm{CO}_2$ . Max press 3800psi, avg 3600psi.				
		Pumped 401 bbls & press increased to 3800psi, pumped 3000gals pad, restarted sd @ 1 1/2#/gal, press				
	increased to 3	300ps <mark>i, s</mark> tarted flus	sh. Pump	ed a total of 721 bbl	ls gild wtr+180 bbls CO <sub>2</sub> carrying	
	55,000# 10-20s	d, 721 BLWTR. ISIP 1	1400psi,	5min 900psi, 10min 9	000ps1, 15min 850ps1.	
hereby certify	that the foregoing	is true and correct	r			
SIGNED /	ne Hobb	¥ τιτι	LE Drill	ing & Production Mana	ager DATE 8-17-83	
	r Federal or State					
tinis space to	HOUGHAI OF STATE	ATTCO USE/				
APPROVED BY		TITL	LE		DATE	
CONDITIONS OF	APPROVAL, IF ANY:				ACCEPTED FOR RECORD	
					$\sim$ $\sim$	

\*See Instructions on Reverse Side

PP AUG 3 1 1983