

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

RECEIVED

Form Approved

458

NOV 14 '88

SUNDRY NOTICES AND REPORTS ON WELLS  
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir). Use "APPLICATION FOR PERMIT" for such proposals.

1. Oil ☐ Gas ☐  
Well ☐ Well ☒ Other ☐

2. NAME OF OPERATOR  
Read & Stevens, Inc.

3. ADDRESS OF OPERATOR  
P.O. Box 1518, Roswell, NM 88202

4. LOCATION OF WELL (Report location clearly and in accordance with State requirements.\*  
See also space 17 below.)  
At surface  
860' FSL & 660' FWL

14. PERMIT NO.  
15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
3907' GR

5. LEASE DESIGNATION AND SERIAL NO.  
NM-18970

6. IF INDIAN, ALLOTTEE OF TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
West Haystack Federal

9. WELL NO.  
2

10. FIELD AND POOL, OR WILDCAT  
Haystack-Cisco

11. SEC. T., R., M., OR BLK. AND  
SURVEY OR AREA  
Sec. 20-6S-27E

12. COUNTY OR PARISH  
Chaves

13. STATE  
NM

16. Check Appropriate Box to Indicate Nature of Notice, Report, Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>	(Other)	<input type="checkbox"/>		<input type="checkbox"/>

(Other) (NOTE: Report results of multiple Completion or Recompletion)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give estimated date of starting any proposed work. If well is directionally drilled give sub-surface locations and measured and true vertical depths for all markers and zones pertinent to this work)\*

Plugged and abandoned subject well 10-29-88 as follows:

- 1) set CIBP at 4,600' w/35' cmt plug on top.
- 2) shot 4 1/2" csg at 3,223' and pulled csg.
- 3) set cmt plugs w/tbg at 3,273'-3,173', 1,500'-1,400', 1,030'-930'; 50' surface plug, tag all plugs w/tbg.
- 4) cut off wellhead and install dry hole marker.

Post ID-2  
11-18-88  
P+ A

I hereby certify that the foregoing is true and correct.

SIGNED John C. Mafey TITLE Petroleum Engineer DATE 11-10-88

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_