STATE OF NEW MEXICO INERGY AND MINERALS DEPARTMENT

HOL MINICIPACE DE		
MB. DF COPIES SECEIVES	3	
DISTRIBUTION		
SANTA FE	1	
FILE	1	_
U.S.G.S.		
LAND OFFICE		
00000		1

us, or corice neces	vi 3	Oi	IL CONSER	VAT	ION DIVKEN	A LANE		
DISTRIBUTIO			P. O.	воха	2088			Form C-103
SANTA FE	- , - 		SANTA FE N	IEW M	1EXICOAPTE 07	4000		Revised 10-1-78
FILE	7	•	C, (, (,),), , , , , , , , , , , , , ,		APR	1982	5a, Indicate Typ	oe of Leuse
U.S.G.S.					* 4. 80		State	Foo X
LAND OFFICE					Ör C	. D.	5. State Oil & G	
OPERATOR					ARTESIA	OFFICE!	N/A	ida Ecdao No.
							TTTTTTT	mmmm
(DO NOT USE THE	SUNDRY	SALS TO DRILL	AND REPORTS	LUG BACK	K TO A DIFFERENT RES	ERVOIR.		
						9	7. Unit Agreeme	ent Name
OIL	WELL X	OTHER-					N/A	
Name of Operator							8. Farm or Leas	
Stevens	Operating	Corporat	cion /				Mitchell	
. Address of Operator							9. Well No.	
P. O. B	ox 2408, R	oswell, N	ทุง 88201				1	
4. Location of Well							10. Field and P	
D	6	60	Nor	th	_ LINE AND	F1.F7 58.0.	Undesign	ated Abo
UNIT LETTER		FEET	FROM THE		_ LINE AND	FEET FROM		
West		9	6 township	S	261	<u> </u>		
THE	LINE, SECTION		TOWNSHIP		RANGE			
mmm	mm	15.	Elevation (Show wh	ether DF	F, RT, GR, etc.)		12. County	MITTELL
3643.9 GR						Chaves		
711111111111111111111111111111111111111	<i></i>	7777Ă	r) or 1 1		C N1 1	P 0 · O	has Data	
				ite Nat	ture of Notice,		ner Data T REPORT OF	
NO	OTICE OF IN	TENTION T	O:			SOBSEQUEN	I REPORT OF	•
	$\overline{}$			r		~		ERING CASING
PERFORM REMEDIAL WOR	* <u> </u>		PLUG AND ABANDON		REMEDIAL WORK	=		=
TEMPORARILY ABANDON	닐			— i	COMMENCE DRILLING O	 1	PLUG	AND ABANDONMENT
FULL OR ALTER CASING			CHANGE PLANS	L)	MAD DAA TEST AND CEMI To blod	ceat. Frac	ture Treat.	Perforations
					OTHER TICEL T	1200		U
OTHER				-				
	- Completed One	rations (Clear	ly state all pertine	nt detail:	s and give pertinent	dates, includin	e estimated date o	starting any proposed
.7. Describe Proposed of work) SEE RULE 1	or Completed Ope 103.	rations (Clear	ty state all perime	ni deibi.	s, and give pertinent			,
•			F // /7	/.7 E	40 5 40 4	0 5 51 5	1 5 72 5	73. 73.5
4-3-82	Perforated	at 3843	.), 44, 4/,	47.5,	48.5, 49, 4	oddied w	//\000	% HCI
			, /8. Packe	er set	at 3784', a	cidized w/	4000 gar /	2/0 IIOD ,
	13700 SCF	N2.						
		1.11)O 37776	20600	ani Cia 1	00000# 207/	in sand.
4-4-82	Frac via	½" casin	g using 4000	JU YFC	co ₂ , 20600	gai CJ2,	10000011 2074	io sana,
	62000# 10/	20 sand,	90 tons CO ₂	2•				
		•						

18. I hereby c	ertify that the information above is true and comp	lete to the best of my knowledge and belief.			
*16HED	The homeson	Production Coordinater	_ DATE	4/6/82	
	mh Wilha	OIL AND GAS INSPECTIVE	DATE	APR	S 19t