Form 9–331	Form Approved.
UNITED STATES UNITED STATES NM OIL CONS. COMMISSION DEPARTMENT OF THE INTERIOR Dragor VO Actoric NN 88210 Cotoric NN 88210	5. LEASE NM 29417 6. IF INDIAN, ALLOTTEE OR TRIBE NAME N/A RECEIVED
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals () 1. oil gas (X) well well other 2. NAME OF OPERATOR STEVENS OPERATING CORPORATION 3. ADDRESS OF OPERATOR P. O. Box 2408, Roswell, NM 88201 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 660 FNL 660 FEL Sec 13 T8S R25E AT TOP PROD. INTERVAL: Same as above	7. UNIT AGREEMENT NAME N/A B. FARM OR LEASE NAME PAUL HICKS FEDERAL 9. WELL NO. 2 ARTESIA, OFFICE 10. FIELD OR WILDCAT NAME Wildcat Abo 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 13, T-8-S, R-25-E 12. COUNTY OR PARISH 13. STATE Chaves NM
AT TOTAL DEPTH: Same as above 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	14. API NO. 30-005-61445 15. ELEVATIONS (SHOW DF, KDB, AND WD) 3563' GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statisticulating estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertine 	directionally drilled, give subsurface locations and
12- 1-82 Ran 38 joints 4½" x 10.5# casing. Se POZ w/2% CC & 110 sxs Class "C" w/2% 1000# for 30 minutes logging no pres	CC. WOC 18 hrs. Pressure up
12- 3-82 Perf @ 1390, 90.5, 91, 91.5 (4 shots set @ 1421'. Spot 4 bbls 15% HCL. P AD-1 tension packer @ 1163' & acidiz	ull 8 joints 2 3/8" tubing. Set
12- 4-82 AD-1 tension packer set @ 1354' (42 HCL.	joints). Acidize w/2000 gal 28%
Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the Gregoing is true and correct Production SIGNED	Set @Ft. DATE December 28, 1982
(ORIG. SGD.) DAVID R GLASS	

See Instructions on Reverse Side

MINERALS MANAGEMENT SERVICE ROSWELL, NEW MEXICO 19 K