

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED

MAR 30 1993

WELL API NO. 30-005-61493
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VB-427

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN A WELL OR TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER RECOMPLETION	7. Lease Name or Unit Agreement Name Hanlad AKZ State
2. Name of Operator YATES PETROLEUM CORPORATION	8. Well No. 1
3. Address of Operator 105 South 4th St., Artesia, NM 88210	9. Pool name or Wildcat Undesignated Wolfcamp
4. Well Location Unit Letter M : 660 Feet From The South Line and 660 Feet From The West Line Section 13 Township 8S Range 27E NMPM Chaves County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3936' GR	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	
OTHER: Perforate, treat Wolfcamp <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well completed in Penn perforations 6327-6411'. Propose to recomple well in Wolfcamp as follows:

- 1) Kill well. POOH w/2-3/8" tubing and packer.
- 2) Set RBP \pm 6250' and test. Run correlation cased hole log - if needed.
- 3) Perforate Wolfcamp 5584-5590' w/2 SPF and 5609-5618' w/1 SPF, from open-hole logs.
- 4) Acidize 5584-5618' with 1500 gals 15% NEFE acid + balls.
- 5) Swab test.
- 6) File recompletion report for Wolfcamp zone.

Will produce Wolfcamp until bottom-hole pressure equals bottom hole pressure in Penn perms 6327-6411', then apply for commingling.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 3-29-93
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY [Signature] SUPERVISOR, DISTRICT II DATE 3-30-93
CONDITIONS OF APPROVAL, IF ANY: