NO. OF COPIES NECES	v15 5				
					Princeco
DISTRIBUTION			T.	RESPOND	Supersedes Old C-102 and C-103
ANTA FE	'	NEW MEXICO OIL CONSE	RVATION C	OMMISSION	Liftentive 1-4-65
ILE				5 Th 25 🐧	
I,S.G.S.				1982	5a. Indicate Type of Lease
AND OFFICE			Ŋ.		State Fee X
PERATOR			3		5. State Off 6 Gas Lease No.
			1	FS(A) (JFe)U	
			· · · · · · · · · · · · · · · · · · ·	******	mmmmm
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.					
OIL X	GAS WELL	OTHEF.			7. Unit Agreement Name
Name of Operator			 		5. Farm or Lease Name
Santa Rita	Explorati	ion Corporation 🗸 👚			Moonshine 7
Address of Operator		1			9. Well No.
P. O. Box	798 A	rtesia, New Mexico	00010		ш т э
ocation of Well	750 A.	resia, New Mexico	00210		#13 - 10. Field and Pool, or Wildoot
UNIT LETTER) 23.	10 FEET FROM THE East	LINE AND	990 FEET FRO	Twin Lakes-SA Assoc
THE South	LINE SECTION	7 TOWNSHIP 9S	BALCE	29E	
	CINE, SECTION_	OWNSHIP	RANGE	NMP	
		15. Elevation (Show whether I)	F, RT, GR, et	c.)	12. County
		3928' GL	. ,		
777777777	77777777777				Chaves (1)
	Check Ap	propriate Box To Indicate Na	ture of No	ice, Report or O	ther Data
Ν	OTICE OF INT				IT REPORT OF:
IFORM REMEDIAL WOR		PING AND ABANION	PINETIA. MAE		ALTERING CASING
	``	PLUG AND ABANDON	REMEDIAL NOT	·	=
APORARILY ABANDON	\sqsubseteq		COMMENCE OR.	L'NG OPKS.	PLUG AND ABANDONMENT
LL OR ALTER CASING		CHANGE PLANS	CASING TEST A	CEMENT JOE X	
LL OR ALTER CASING		CHANGE PLANS	CASING TEST A		
OTHER		CHANGE PLANS			
OTHER			OTHER		
OTHER			OTHER		r estimated date of starting any proposed
OTHER			OTHER		r estimated date of starting any proposed
OTHER Describe Proposed			OTHER		y estimate! date of starting any proposed
OTHER	1103.	stions (Clearly state all pertinent detail	other	ctinent dates, includin	
OTHER	1103.		other	ctinent dates, includin	
Describe Proposed work) SEE RULE 1	WOC-18 ho	Durs. Pressure test	other	ctinent dates, includin	
Describe Proposed work) SEE RULE 1	WOC-18 ho	stions (Clearly state all pertinent detail	other	ctinent dates, includin	
Describe Proposed work) SEE RULE 1	WOC-18 ho	ours. Pressure test	other	ounem dates, includin	mins. Held fine.
Describe Proposed work) SEE RULE 1	WOC-18 ho Drilled t	ours. Pressure test to TD of 2793'. of 4½", 10.5# casi	of 1,0	00# for 30 mented with	mins. Held fine. 600 sxs. of Halliburt
Describe Proposed work) SEE RULE 1	WOC-18 ho Drilled t	ours. Pressure test to TD of 2793'. of 4½", 10.5# casi	of 1,0	00# for 30 mented with	mins. Held fine. 600 sxs. of Halliburt
Describe Proposed work) SEE RULE 1	WOC-18 ho Drilled t Ran 2742' lite and	ours. Pressure test to TD of 2793'. of 4½", 10.5# casi 400 sxs. of 50/50 p	of 1,0	00# for 30 mented with	mins. Held fine. 600 sxs. of Halliburt
Describe Proposed work) SEE RULE 1	WOC-18 ho Drilled t Ran 2742' lite and salt. Ce	ours. Pressure test to TD of 2793'. of 4½", 10.5# casi 400 sxs. of 50/50 pement did not circul	of 1,0 ng. Ce oz.mix ate.	mented with	mins. Held fine. 600 sxs. of Halliburt
Describe Proposed work) SEE RULE 1	WOC-18 ho Drilled t Ran 2742' lite and salt. Ce	ours. Pressure test to TD of 2793'. of 4½", 10.5# casi 400 sxs. of 50/50 p	of 1,0 ng. Ce oz.mix ate.	mented with	
Describe Proposed work) SEE RULE 1	WOC-18 ho Drilled t Ran 2742' lite and salt. Ce	ours. Pressure test to TD of 2793'. of 4½", 10.5# casi 400 sxs. of 50/50 pement did not circul	of 1,0 ng. Ce oz.mix ate.	mented with	mins. Held fine. 600 sxs. of Halliburt
Describe Proposed work) SEE RULE 1	WOC-18 ho Drilled t Ran 2742' lite and salt. Ce	ours. Pressure test to TD of 2793'. of 4½", 10.5# casi 400 sxs. of 50/50 pement did not circul	of 1,0 ng. Ce oz.mix ate.	mented with	mins. Held fine. 600 sxs. of Halliburt
Describe Proposed work) SEE RULE 1	WOC-18 ho Drilled t Ran 2742' lite and salt. Ce	ours. Pressure test to TD of 2793'. of 4½", 10.5# casi 400 sxs. of 50/50 pement did not circul	of 1,0 ng. Ce oz.mix ate.	mented with	mins. Held fine. 600 sxs. of Halliburt
Describe Proposed work) SEE RULE 1	WOC-18 ho Drilled t Ran 2742' lite and salt. Ce	ours. Pressure test to TD of 2793'. of 4½", 10.5# casi 400 sxs. of 50/50 pement did not circul	of 1,0 ng. Ce oz.mix ate.	mented with	mins. Held fine. 600 sxs. of Halliburt
Describe Proposed work) SEE RULE 1	WOC-18 ho Drilled t Ran 2742' lite and salt. Ce	ours. Pressure test to TD of 2793'. of 4½", 10.5# casi 400 sxs. of 50/50 pement did not circul	of 1,0 ng. Ce oz.mix ate.	mented with	mins. Held fine. 600 sxs. of Halliburt
Describe Proposed work) SEE RULE 1	WOC-18 ho Drilled t Ran 2742' lite and salt. Ce	ours. Pressure test to TD of 2793'. of 4½", 10.5# casi 400 sxs. of 50/50 pement did not circul	of 1,0 ng. Ce oz.mix ate.	mented with	mins. Held fine. 600 sxs. of Halliburt
Describe Proposed work) SEE RULE 1	WOC-18 ho Drilled t Ran 2742' lite and salt. Ce	ours. Pressure test to TD of 2793'. of 4½", 10.5# casi 400 sxs. of 50/50 pement did not circul	of 1,0 ng. Ce oz.mix ate.	mented with	mins. Held fine. 600 sxs. of Halliburt
Describe Proposed work) SEE RULE 1	WOC-18 ho Drilled t Ran 2742' lite and salt. Ce	ours. Pressure test to TD of 2793'. of 4½", 10.5# casi 400 sxs. of 50/50 pement did not circul	of 1,0 ng. Ce oz.mix ate.	mented with	mins. Held fine. 600 sxs. of Halliburt
Describe Proposed work) SEE RULE 1	WOC-18 ho Drilled t Ran 2742' lite and salt. Ce	ours. Pressure test to TD of 2793'. of 4½", 10.5# casi 400 sxs. of 50/50 pement did not circul	of 1,0 ng. Ce oz.mix ate.	mented with	mins. Held fine. 600 sxs. of Halliburt
Describe Proposed work) SEE RULE 1	WOC-18 ho Drilled t Ran 2742' lite and salt. Ce	ours. Pressure test to TD of 2793'. of 4½", 10.5# casi 400 sxs. of 50/50 pement did not circul	of 1,0 ng. Ce oz.mix ate.	mented with	mins. Held fine. 600 sxs. of Halliburt
Describe Proposed work) SEE RULE 1	WOC-18 ho Drilled t Ran 2742' lite and salt. Ce	ours. Pressure test to TD of 2793'. of 4½", 10.5# casi 400 sxs. of 50/50 pement did not circul	of 1,0 ng. Ce oz.mix ate.	mented with	mins. Held fine. 600 sxs. of Halliburt
Describe Proposed work) SEE RULE 1 5-24-82 5-26-82 5-27-82	WOC-18 ho Drilled t Ran 2742' lite and salt. Co Rig down	ours. Pressure test to TD of 2793'. of 4½", 10.5# casi 400 sxs. of 50/50 pement did not circul and waiting on comp	of 1,0 ng. Ce oz.mix ate. letion	mented with Class "C",	mins. Held fine. 600 sxs. of Halliburt
Describe Proposed work) SEE RULE 19 5-24-82 5-26-82 5-27-82	WOC-18 ho Drilled t Ran 2742' lite and salt. Co Rig down	ours. Pressure test to TD of 2793'. of 4½", 10.5# casi 400 sxs. of 50/50 pement did not circul	of 1,0 ng. Ce oz.mix ate. letion	mented with Class "C",	mins. Held fine. 600 sxs. of Halliburt
Describe Proposed work) SEE RULE 19 5-24-82 5-26-82 5-27-82	WOC-18 ho Drilled t Ran 2742' lite and salt. Co Rig down	ours. Pressure test to TD of 2793'. of 4½", 10.5# casi 400 sxs. of 50/50 perment did not circul and waiting on comp	of 1,0 ng. Ce oz.mix ate. letion	mented with Class "C",	mins. Held fine. 600 sxs. of Halliburt 83 salt, 2% Gel and 5
Describe Proposed work) SEE RULE 1 5-24-82 5-26-82 5-27-82	WOC-18 ho Drilled t Ran 2742' lite and salt. Co Rig down	ours. Pressure test to TD of 2793'. of 4½", 10.5# casi 400 sxs. of 50/50 perment did not circul and waiting on comp	of 1,0 ng. Ce oz.mix ate. letion	mented with Class "C",	mins. Held fine. 600 sxs. of Halliburt
Describe Proposed work) SEE RULE 1 5-24-82 5-26-82 5-27-82	WOC-18 ho Drilled t Ran 2742' lite and salt. Co Rig down	ours. Pressure test to TD of 2793'. of 4½", 10.5# casi 400 sxs. of 50/50 perment did not circul and waiting on comp	of 1,0 ng. Ce oz.mix ate. letion	mented with Class "C",	mins. Held fine. 600 sxs. of Halliburg 83 salt, 2% Gel and 5
Describe Proposed work) SEE RULE 1 5-24-82 5-26-82 5-27-82	WOC-18 ho Drilled t Ran 2742' lite and salt. Co Rig down	ours. Pressure test to TD of 2793'. of 4½", 10.5# casi 400 sxs. of 50/50 perment did not circul and waiting on comp	of 1,0 ng. Ce oz.mix ate. letion	mented with Class "C",	mins. Held fine. 600 sxs. of Halliburt 83 salt, 2% Gel and 5

CONDITIONS OF APPROVAL, IF ANY: