

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

c/sf
bp

Form C-103
Revised March 25, 1999

WELL API NO. 30005-61622
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: Twin Lakes San Andres Unit
7. Well No. 114
8. Pool name or Wildcat Twin Lakes; San Andres (Assoc)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐ Injection ☐	
2. Name of Operator Concho Oil & Gas Corp.	
3. Address of Operator 110 W. Louisiana Ste 410; Midland, Tx 79701	
4. Well Location Unit Letter <u>P</u> : <u>990</u> Feet from the <u>South</u> line and <u>990</u> feet from the <u>East</u> line Section <u>7</u> Township <u>9S</u> Range <u>29E</u> NMPM <u>Chaves</u> County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3928 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Concho Oil & Gas Corp. respectfully requests approval to plug and abandon the TLSAU #114 well according to the following procedure:

1. Notify NMOCD Artesia 24 hrs prior to commencement of procedure:
2. RIH & set 150' cmt plug @ ~~2680-2830~~ ^{2639 to 2860} WOC. Tag.
Circ hole w/ mud.
4. Set 100' plug @ 2050-2150'.
5. Set 100' cmt plug @ ~~1635-1735~~ ^{1400' to 150'}.
6. Set 100' cmt plug @ 965-1065'.
7. Perf csg @ 230'. Squeeze w/ 25 sx.
8. Circ cmt from 230' to surface.
9. Cut off wellhead & install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terri Stathem TITLE Production Analyst DATE 9-28-01

Type or print name Terri Stathem Telephone No. 915/683-7443

(This space for State use)

APPROVED BY [Signature] TITLE Wild Sup ID DATE 10-10-01
Conditions of approval, if any:


TLSAU #114

Formerly - Moonshine 7 #14

Lease No.: 24988 Dist. No.: County: Chaves Field: Twin Lakes San Andres
 Section: 7 Twsp: 9S Range: 29E Unit Ltr: P Location: 990' FSL & 990' FEL

API No. 30-005-61622

Spud Date: 05/29/82
 TD Date: 06/02/82
 Comp Date: 09/02/82



Original Perf Details: 2797, 98, 2802, 02.5, 03, 03.5
 5000 gals 20% acid

Aug-82 Sqz'd P2 perms w/ 300 sx
 P1: 2739, 40, 44, 48, 49, 50, 54, 57, 58, 59, 64, 65, 66, 67, 68, 69, 70, 71, 72
 Acdz'd w/ 6000 gals 20%

Well Unit P Twin Lakes SA Unit # 114
Section 7 Township Range 29
API # 30 - 005 - 61622

- Salt gel mud consisting of 10# brine with 25# of gel per barrel must be placed between each plug
- Install Dry Hole Marker

* Notify OCD 24 hrs. prior to any work done

