Form 9-331 Dec. 1973	• \.		
	UNUTED STATES	5. LEASE NR. 10000	1.1
	DEPARTMENT OF THE INTERIOR	B210 NM 18822	E.
	GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
	MIN DEPORTECON WELLS	7. UNIT AGREEMENT NAME	
SUNDR'	Y NOTICES AND REPORMECENCE WELLS form for proposals to drill or to deepen or plug back to a different form 9-331-C for such proposals.)		1
eservoir. Use Fo		8. FARM OR LEASE NAME Leeman OC Federal	
1. oil well	gas well to ther OCT 2 2 1982	9. WELL NO.	
2. NAME O	F OPERATOR O. C. D	4 10. FIELD OR WILDCAT NAME	¥
	Yates Petroleum Corp annesia n Office	Pecos Slope Abo	
3. ADDRESS	S OF OPERATOR 207 South 4th St., Artesia, NM 88210	11. SEC., T., R., M., OR BLK. AND SURVEY OR	i
4. LOCATIO	N OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA Unit D, Sec. 20-T7S-R26E	
below.) At surf	ACE: 660 FNL & 990 FWL, Sec. 20-7S-26E	12. COUNTY OR PARISH 13. STATE	-
ΑΤ ΤΟΡ	PROD. INTERVAL:	Chaves NM	191. 211-24
	L DEPTH: APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.	
16. CHECK A	, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)	F
		3577' GR	
REQUEST FO			
FRACTURE 1			
SHOOT OR A	L D L	(NOTE: Report results of martiple completion or zone change on Form 9–330.)	
PULL OR AL MULTIPLE C			1. 1.
CHANGE ZO			
ABANDON* (other)		INNETALS MEMT. SERVICE Roswell, New Mexico	
includin	BE PROPOSED OR COMPLETED OPERATIONS (Clearly sta g estimated date of starting any proposed work. If well is	ant to this work)*	
includin measur 4575'. ide shoe % CF-9, . essure ar cesetter les as fo	BE PROPOSED OR COMPLETED OPERATIONS (Clearly stage stimated date of starting any proposed work. If well is ed and true vertical depths for all markers and zones pertine Ran 114 jts of 4-1/2" 9.5# J-55 casing set 4575'. Float collar set 4535'. Co .3% TF-4 and 2% KCL. PD 2:00 PM 8-28-88 and float held okay. WOC. Ran 1512' of Lite Neat. PD 5:00 PM 8-28-82. WIH at ollows: 3832-36' (5 holes) 3861-65' (5 w/1000 gallons 7½% acid. Frac'd perfo 20 tons CO2, 400# block, 40000# 20/40	ent to this work.)* set 4575'. 1-Texas Pattern notched emented w/400 sacks 50/50 Poz, 2. Bumped plug to 1000 psi, released 1" pipe. Cemented w/375 sacks nd perforated 3832-3865' w/10 .50" holes). Acidized perforations rations w/20000 gallons gelled	
includin measur (4575'. (1) de shoe (2) CF-9, (2) cessure an (2) c	<pre>g estimated date of starting any publicate and zones pertine ed and true vertical depths for all markers and zones pertine Ran 114 jts of 4-1/2" 9.5# J-55 casing set 4575'. Float collar set 4535'. Co .3% TF-4 and 2% KCL. PD 2:00 PM 8-28-80 nd float held okay. WOC. Ran 1512' of Lite Neat. PD 5:00 PM 8-28-82. WIH at ollows: 3832-36' (5 holes) 3861-65' (5 w/1000 gallons 7½% acid. Frac'd perfo 20 tons CO2, 400# block, 40000# 20/40</pre>	<pre>ent to this work.)* set 4575'. 1-Texas Pattern notched emented w/400 sacks 50/50 Poz, 2. Bumped plug to 1000 psi, released 1" pipe. Cemented w/375 sacks nd perforated 3832-3865' w/10 .50" holes). Acidized perforations rations w/20000 gallons gelled sand. Set @ Ft.</pre>	
includin measur 4575'. iide shoe % CF-9, eessure an icesetter oles as fo 32-3865' CL water, Subsurface 18. Thereb	and true vertical depths for all markers and zones pertine Ran 114 jts of 4-1/2" 9.5# J-55 casing set 4575'. Float collar set 4535'. Co .3% TF-4 and 2% KCL. PD 2:00 PM 8-28-89 and float held okay. WOC. Ran 1512' of Lite Neat. PD 5:00 PM 8-28-82. WIH at ollows: 3832-36' (5 holes) 3861-65' (5 w/1000 gallons 7 ¹ / ₂ % acid. Frac'd perfo 20 tons CO ₂ , 400# block, 40000# 20/40 Safety Valve: Manu. and Type	Set <u>Sect</u> <u>Set</u> <u>10-11-82</u>	
includin measur 4575'. ide shoe % CF-9, . essure an cesetter les as fo 32-3865' % water, % Subsurface	and true vertical depths for all markers and zones pertine Ran 114 jts of 4-1/2" 9.5# J-55 casing set 4575'. Float collar set 4535'. Co .3% TF-4 and 2% KCL. PD 2:00 PM 8-28-89 and float held okay. WOC. Ran 1512' of Lite Neat. PD 5:00 PM 8-28-82. WIH at ollows: 3832-36' (5 holes) 3861-65' (5 w/1000 gallons 7 ¹ / ₂ % acid. Frac'd perfo 20 tons CO ₂ , 400# block, 40000# 20/40 Safety Valve: Manu. and Type	Set <u>Sect</u> <u>Set</u> <u>10-11-82</u>	A TANK AND A TANKA A TA
includin measur 4575'. ide shoe % CF-9, . essure an cesetter les as fo 32-3865' % Water, % Subsurface 18. Thereb signer.	and true vertical depths for all markers and zones pertine Ran 114 jts of 4-1/2" 9.5# J-55 casing set 4575'. Float collar set 4535'. Co .3% TF-4 and 2% KCL. PD 2:00 PM 8-28-80 and float held okay. WOC. Ran 1512' of Lite Neat. PD 5:00 PM 8-28-82. WIH at ollows: 3832-36' (5 holes) 3861-65' (5 w/1000 gallons 7 ¹ / ₂ % acid. Frac'd perfo 20 tons CO ₂ , 400# block, 40000# 20/40 Safety Valve: Manu. and Type	Set <u>Sect</u> <u>Set</u> <u>10-11-82</u>	
includin measur 4575'. ide shoe % CF-9, . essure an cesetter les as fo 32-3865' % Water, % Subsurface 18. Thereb signer.	and true vertical depths for all markers and zones pertine Ran 114 jts of 4-1/2" 9.5# J-55 casing set 4575'. Float collar set 4535'. Co .3% TF-4 and 2% KCL. PD 2:00 PM 8-28-80 and float held okay. WOC. Ran 1512' of Lite Neat. PD 5:00 PM 8-28-82. WIH at ollows: 3832-36' (5 holes) 3861-65' (5 w/1000 gallons 7 ¹ / ₂ % acid. Frac'd perfo 20 tons CO ₂ , 400# block, 40000# 20/40 Safety Valve: Manu. and Type by certify that the foregoing is true and correct Correct the foregoing is true and correct Correct for the foregoing is true and correct for the foregoing is true and correct Correct for the foregoing is true and correct for the foregoing	<pre>ent to this work.)* set 4575'. 1-Texas Pattern notched emented w/400 sacks 50/50 Poz, 2. Bumped plug to 1000 psi, released 1" pipe. Cemented w/375 sacks nd perforated 3832-3865' w/10 .50" holes). Acidized perforations rations w/20000 gallons gelled sand. Set @ Ft. </pre>	
includin measur 4575'. iide shoe % CF-9, cessure an icesetter oles as fo 32-3865' CL water, Subsurface 18. Thereb	and true vertical depths for all markers and zones pertine Ran 114 jts of 4-1/2" 9.5# J-55 casing set 4575'. Float collar set 4535'. Co .3% TF-4 and 2% KCL. PD 2:00 PM 8-28-80 and float held okay. WOC. Ran 1512' of Lite Neat. PD 5:00 PM 8-28-82. WIH at ollows: 3832-36' (5 holes) 3861-65' (5 w/1000 gallons 7 ¹ / ₂ % acid. Frac'd perfo 20 tons CO ₂ , 400# block, 40000# 20/40 Safety Valve: Manu. and Type ov certify that the foregoing is true and correct Correct Correct Correct Correct CORIG. SGD.) DAVID (Riscing agess Federal or State BY S OF APPROV OCT ATY 9 1982 U.S. GEOLOGICAL SURVEY DOSMELL NEW MEXICO	<pre>ent to this work.)* set 4575'. 1-Texas Pattern notched emented w/400 sacks 50/50 Poz, 2. Bumped plug to 1000 psi, released 1" pipe. Cemented w/375 sacks nd perforated 3832-3865' w/10 .50" holes). Acidized perforations rations w/20000 gallons gelled sand</pre>	
includin measur) 4575'. nide shoe 5% CF-9, . cessure an acesetter oles as fo 332-3865' CL water, Subsurface 18. Thereb	Ran 114 jts of 4-1/2" 9.5# J-55 casing set 4575'. Float collar set 4535'. Cl .3% TF-4 and 2% KCL. PD 2:00 PM 8-28-80 nd float held okay. WOC. Ran 1512' of Lite Neat. PD 5:00 PM 8-28-82. WIH at ollows: 3832-36' (5 holes) 3861-65' (5 w/1000 gallons 7 ¹ / ₂ % acid. Frac'd perfo 20 tons CO ₂ , 400# block, 40000# 20/40 Safety Valve: Manu. and Type ov certify that the foregoing is true and correct ACCEPTED FOR RECORD (ORIG. SGD.) DAVID (Riscing ages Federal or State BY S OF APPROV OCT ATY 9 1982 ITLE	<pre>ent to this work.)* set 4575'. 1-Texas Pattern notched emented w/400 sacks 50/50 Poz, 2. Bumped plug to 1000 psi, released 1" pipe. Cemented w/375 sacks nd perforated 3832-3865' w/10 .50" holes). Acidized perforations rations w/20000 gallons gelled sand</pre>	