

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

SEP 11 1991

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO.
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator WALLACE OIL & GAS INC.		6. State Oil & Gas Lease No.
3. Address of Operator 50 PENN PLACE, STE 850 OKLA, CITY, OK 73118		7. Lease Name or Unit Agreement Name PAYTON
4. Well Location Unit Letter <u>J</u> : 1980 Feet From The <u>EAST</u> Line and 1980 Feet From The <u>SOUTH</u> Line Section <u>8</u> Township <u>11-S</u> Range <u>25-E</u> NMPM CHAVES County		8. Well No. 1
10. Elevation (Show whether DF, RKB, RT, GR, etc.)		9. Pool name or Wildcat WILDCAT <u>S. Paces Slope Abo</u>

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. SET 4½ CIBP AT 3950'
2. SPOT 25 SKS CEMENT PLUG ON TOP OF 4½ CIBP AT 3950'
3. CUT AND PULL 4½ CASING AT 2773'
4. SPOT 30 SKS CEMENT PLUG AT 4½ STUB 2823' AND W.O.C.
5. TAGGED PLUG AT 2681'
6. SPOT 90 SKS CEMENT PLUG AT 1445' PLUG COVERED GLORIETTA 8 5/8 SHOE W.O.C.
7. TAGGED PLUG AT 1226'
8. SPOT 25 SKS CEMENT PLUG AT 1226'
9. SPOT 30 SKS CEMENT PLUG AT 740'
10. SPOT 30 SKS CEMENT PLUG AT 506'
11. SPOT 15 SKS CEMENT PLUG AT SURF. AND SET UP P&A MARKER
12. HOLE WAS LOADED WITH BRINEGEL.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Raymond Maldonado TITLE P&A SUPERVISOR DATE 8-30-91
TYPE OR PRINT NAME RAYMOND MALDONADO TELEPHONE NO. (505)393-5516

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep DATE 10/15/91
CONDITIONS OF APPROVAL, IF ANY: