## P. O. BRANER OD ARTESIA, NEW MEXICO 88210

	•	DATE	8/22/	<b>73</b>
Ma	obil Prod. Tx NM INC			
nineq	reenway plaza, ste. 2700			
_	uston, Tx. 77046			
Gentlemen:		Re: P	lugging Reports	
Form C-1	03, Report of Plugging for your <u>K.S.W</u> c			
מייה בי נייי	be approved until a Division representation of the cleared to comply with Division in the space provided to indicate that	on Rules a	ua kadatariona.	of the locatio Please check
( ) 1.	All pits have been filled and leveled.			
( ) 2.	Rat hole and cellar have been filled and	d leveled.	-	
	A steel marker 4" in diameter and approbeen set in concrete. It must show the designation, section, township and rang stenciled or welded on the marker.	e numbers	which have beer	permanently
( ) 4.	The location has been leveled as nearly contour and has been cleared of all jun	as possib k and equi	le to original pment.	top ground
( ) 5.	The dead men and tie downs have been cu	t and remo	ved.	
( ) 6.	If a one well lease or last remaining w locations have been leveled and cleared	ell on lea of all ju	se, the battery nk and equipmer	and burn pit it.
The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.				
filling	l of the work outlined above has been don in the blank form below and returning th ill not have to make more than one trip t	is letter	to as so chat t	fice by our represent-
	. •	OIL CO	NSERVATION DIV	. ISION
CT1	BELOW AND RETURN	DIŞTRÎ	Jamos CT GEÓLOGIST	evo's
I certi	fy that the above work has been done and	the		
	is ready for your insp	Le pe <b>ction</b> and	ase Lapproval.	
Well No	. Unit S-T-R			
•		Opena	itor	