CRGY AND MINICHALS D	EPAH	HIVIE
HO. OF COTIES RECEIVED	T	
MOITHBUTION		
SANTA FE	1	
PILE	1	1
U.S.O.S.		1
LAND OFFICE		
OPPRATOR	11/	1 1

OIL CONSERVATION DIVISION

Form	C-	103	
Revis	e d	10-	1 - 7

DISTRIBU	P.O. BOX 2006 194	Revised 10-1-78		
SANTA FE	SANTA FE, NEW MEXICO 87501			
\		5a. Indicate Type of Lease		
PILE	JAN 25 1983	State Fee X		
LAND OFFICE		5. State Oll & Gas Lease No.		
OPERATOR	0. C. D.			
OPERATOR.	ARTSSIA, OFFICE	mmmmmm.		
	SUIDON NOTICES AND DEPORTS ON WELLS			
	SUNDRY NOTICES AND REFORM OF PLUG BACK TO A DIFFERENT RESERVOIR. E THIS FORM FOR PROPOSALS TO CRILL OR TO GEEFEN OF PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.)			
(86 NOT V3	USE "APPLICATION FOR PERMIT -" (FORM CHIOTYTO)	7. Unit Agreement Name		
	٠٠٠ (٣٦			
01L	WELL XX OTHER-	8. Farm of Lease Name		
; iame of Operator	V	Sun-Diamond		
STEVENS OF	g. Well No.			
Address of Opera	ator	1		
Address of Open	44 37 Managan 88/111			
		10. Field and Pool, or Wildcat		
. Location of Well	South 1980 FEET	Pecos Slope Abo		
UNIT LETTER	O 660 FEET FROM THE SOUTH LINE AND 1980 FEET F			
	7.2 26F	<i>XIIIIIIIIII</i>		
Eas		···· (;[]]]]]]]]]]]]		
THE		12. County		
$mm\pi$	15. Elevation (Show whether DF, RT, GR, etc.)	Chaves		
	3566.8 GR	Ollaves (//////////		
	Check Appropriate Box To Indicate Nature of Notice, Report or	Other Data		
15.	Check Appropriate Box to indicate Nature of Notice, subsequ	ENT REPORT OF:		
	NOTICE OF INTENTION TO:			
		ALTERING CASING		
PERFORM REMEDIAL	PLUG AND ABANDON REMEDIAL WORK	PLUG AND ABANDONMENT		
	COMMENCE DRILLING OFFIS.	PEGG AND NORMED		
TEMPORARILY ABAN	CHANGE PLANS CASING TEST AND CEMENT SAS	$\overline{\mathbf{x}}$		
PULL OR ALTER CAS	OTHERcasing & ceme	ent K		
OTHER		I law of menting any proposed		
	posed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incli	uding estimated date of starting any proposed		
7, Describe Prop work) SEE RU				
20,	Set 80' of 14" conductor pipe and cement w/200 sxs Class	"C" w/2% CC. Circ. 25 sxs.		
1- 5-83	Set 80' of 14" conductor pipe and cement w/200 sks class	., =		
1 3 03	WOC 18 hrs.			
	1100 10 110			
	Spud @ 9:00 P.M.			
1- 7-83	Spud @ 3.00 1	10.00 DO7 and		
1- 8-83 Ran 24 joints 8 5/8" x 24# casing. Set and cement @ 910' w/450 sxs 50/50 POZ and				
1- 8-83 Ran 24 joints 8 5/8" x 24# casing. Set and cement e 710 w/ 1000# for 30 minutes 300 sxs Class "C". Circ. 75 sxs. WOC 18 hrs. Pressure up 1000# for 30 minutes				
300 sxs Class "C". Circ. 73 sxs. Woo 10 Here				
	logging no pressure decrease.			
	A C A /280' w	7/350 sxs 50/50 POZ w/2% CC.		
1-17-83 Ran 105 joints 4½" x 11.6# casing. Set & cement @ 4280' w/350 sxs 50/50 POZ w/2% CC. WOC 18 hrs. Pressure up 1000# for 30 minutes logging no pressure decrease.				
1-11-03	WOC 18 hrs. Pressure up 1000# for 30 minutes logging no p	/1000010		
	NOO			

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. January 23, 1983 Production Controller Original Signed By JAN 2 6 1983 Leslia A. Clements