

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.D.S.	
LAND OFFICE	
OPERATOR	

IL CONSERVATION DIVISION  
P. O. BOX 2080  
SANTA FE, NEW MEXICO 87501

RECEIVED BY  
JAN 09 1984  
O. C. D.  
ARTESIA, OFFICE

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
NA

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

BILL G. ISLER

Address of Operator

123 Three Cross  
Roswell, New Mexico 88201

Location of Well

UNIT LETTER O 430' FEET FROM THE South LINE AND 1850' FEET FROM  
THE East LINE, SECTION 20 TOWNSHIP 10S RANGE 28E NMPM.

7. Unit Agreement Name

NA

8. Farm or Lease Name

Isler

9. Well No.

3

10. Field and Pool, or Wildcat

Undesignated  
L.E. Ranch-San Andres

15. Elevation (Show whether DF, RT, GR, etc.)  
3744.6 G.L.

12. County

Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

REMEDIAL WORK ☐

ALTERING CASING ☐

PULL OR ALTER CASING ☐

CHANGE PLANS ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

OTHER ☐

CASING TEST AND CEMENT JOBS ☒

OTHER Pulling water shut-off string ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

December 13, 1983 - Ran 425' of 8-5/8", 24# surface casing with cement circulated to the surface.  
Pulled 10-3/4" water shut-off string (156')

Drilled to 2377' and found San Andres zone non-commercial.

Propose to abandon as follows:

1. Set cement plug from 2377' to 2000', isolating San Andres porosity zone.
2. Set cement plug 1200' to 1100', across top of Queen formation.
3. Set cement plug 475' to 375', across surface casing shoe.\* + Tag
4. Clean location and leave upper hole for water well.  
Landowner agreement was mailed to you under separate cover.
5. File Subsequent Report of Abandonment and C-105 after plugging has been accomplished.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

Jerry H. Long  
JERRY W. LONG

TITLE Agent

DATE December 30, 1983

APPROVED BY

Mike Walker

TITLE

OIL AND GAS INSPECTOR

DATE

JAN 04 1984

CONDITIONS OF APPROVAL, IF ANY: \*As Noted Above

Be to witness

Plugging