

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

RECEIVED BY
DEC 06 1984
O. C. D.
ARTESIA, OFFICE

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P&A	7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation	8. Farm or Lease Name Alpha "AAA"
3. Address of Operator 207 South 4th St., Artesia, NM 88210	9. Well No. 1
4. Location of Well UNIT LETTER K 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 23 TOWNSHIP 3S RANGE 29E NMPM.	10. Field and Pool, or Wildcat Wildcat Granite
15. Elevation (Show whether DF, RT, GR, etc.) 4334' GR	12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐
PLUG AND ABANDON ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 8100'. Propose to plug and abandon well as follows:

1. Set CIBP at 7800' w/35' cement.
2. Set CIBP at 7250' w/35' cement.
3. Cut and pull 5½" casing at 6325'.
4. Set 50 sx cement plug 50' in and 50' out of 5½" stub and tag.
5. Set 35 sx cement plug at 4400-4300'.
6. Set 35 sx cement plug at 2400-2300' (8-5/8" shoe) and tag.
7. Set 35 sx cement plug at 420-320'.
8. Set 15 sx cement plug at surface.

Verbal permission obtained 12-6-84 for plugging from Larry Brooks, NMOCD, Artesia.
Notify NMOCD, Artesia, before plugging well.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Larry Brooks

TITLE Production Supervisor

DATE 12-6-84

APPROVED BY BY LARRY BROOKS
GEOLOGIST - NMOCD

TITLE _____

DATE DEC 14 1984

CONDITIONS OF APPROVAL, IF ANY: