

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

NM Oil Cons. Commission

Drawer DD

Artesia, NM 88214


SUBMIT ON DUPLICATE  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 1004-0-1-1  
Expires August 31, 1985

C/SF

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)



1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. NAME OF OPERATOR

McClellan Oil Corporation

3. ADDRESS OF OPERATOR

P.O. Drawer 730, Roswell, NM 88202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

1980' FNL & 990' FWL

JUN 2 1987

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3820' G.L.

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Coyote Draw Federal

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

Pecos Slope Abo

11. SEC., T., R., M., OR BLM, AND  
SURVEY OR AREA

Sec. 30-T7S-R25E

12. COUNTY OR PARISH 13. STATE

Chaves

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

X

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

5/30/87: Plugged and abandoned as follows:

1st plug across Abo top at 3536'. WOC - 2 hours, tagged cement top at 3400'.  
2nd plug across 8-5/8" shoe, set at 1375'. WOC - 2 hours, tagged cement top at 1200'.  
3rd plug set at 50' from surface. Install dry hole marker.  
All plugs were Class C with 2% CaCl<sub>2</sub> with mud between plugs. Will clean location when pits dry.

Post ID-2  
8-7-87  
P+H

18. I hereby certify that the foregoing is true and correct

SIGNED

*Paul Kazdale*

TITLE

Operations Manager

DATE

6/1/87

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

Approved as to plugging of the well bore.  
Liability under bond is retained until  
surface restoration is completed.

\*See Instructions on Reverse Side

APPROVED

PETER W. CHESTER

JUL 28 1987

BUREAU OF LAND MANAGEMENT  
WELL RESOURCE AREA