STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE	_	L
OPERATOR		l

2. Name of Operator

87501

40. 0F COPIES SCEEIVED	OIL CONSERVATION D
DISTRIBUTION	P. O. BOX 2088
SANTA FE	SANTA FE, NEW MEXICO
FILE 1	•
U.S.O.S.	
LAND OSTICE	

OIL CONSERVATION DIVISION	
D C COV 2008	Form C-103
DISTRIBUTION P. O. BOX 2088	Revised 10-1-78
SANTA FE, NEW MEXICO 87501	a. Indicate Type of Lease
U,s.o.s.	State X Fee
	5. State Oil & Gas Lease No.
OPERATOR	LG-5242
TO THE PERSON OF	
SUNDRY NOTICES AND REPORTS ON WELLS DECEIVED TO DRILL ON TO DEEPEN OR PLUG BACK TO A DISTEMBLA VOIR.	
USE "APPLICATION FOR PEHMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7, Unit Agreement Name
	,
WELL OTHER P&A JUL 13'88	8, Farm or Lease Name
Name of Operator	
Vates Petroleum Corporation /	Brunner Pan American AFK
0, C. U.	9. Well No. State
105 South 4th St., Artesia, NM 88210 ARTESIA. OFFICE	. 1
	10. Field and Pool, or Wildcat
I, Location of Well	Und. Diablo San Andres
UNIT LETTER 0 330 FEET FROM THE SOUTH LINE AND 2310 FEET FROM	minimize in the second
· · · · · · · · · · · · · · · · · · ·	
THE East LINE, SECTION 9 TOWNSHIP 10S NAMES 27E NAMPH.	
	7777777777747474
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3866.5' GR	Chaves
White Program of Oth	or Dota
Check Appropriate Box To Indicate Nature of Notice, Report or Other	DEBORT OF
NOTICE OF INTENTION TO: SUBSEQUENT	REPORT OF:
	<u>ر</u> ــا
PERFORM REMEDIAL WORK	ALTERING CASING
COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JQB	<u> </u>
PULL OR ALTER CASING CHANGE PLANS	
OTHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including of	estimated date of starting any proposed
work) SEE RULE 1103.	
near the property of the second of the secon	s from
TD 2203'. Propose to P&A well by spotting 100' (35 sx) cement plugg	n' to
1442' to 1542' (San Andres), from 910' to 1010' (Queen) and from 410	oulstion
510' (8-5/8" shoe). Shoe plug will be tagged. Set 15 sacks and reg	Rutarion

TD 2203'. Propose to P&A well by spotting 100' (35 sx) 1442' to 1542' (San Andres), from 910' to 1010' (Queen) 510' (8-5/8" shoe). Shoe plug will be tagged. Set $15 \, \mathrm{s}$ abandonment marker at surface. Mud between all plugs

Verbal approval given by Mr. Mike Williams, NMOCD, Artesia, NM on 7-11-88. Notify NMOCD 24 hours before plugging.

·	•			•
18. I hereby certify that the information above is true and comple	te to the b	est of my knowledge and belief.		
in and orders	TITLE	Production Supervisor	DATE	7-11-88
Mike Welliams	*! *! *	OIL AND GAS INSPECTOR	DATE	JUL 15 1988
CONDITIONS OF APPROVAL, IF ANY:				
CONDITIONS OF APPROVAL, IF ANY:				