

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. LG 5242

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

RECEIVED

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P&A	7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation	8. Farm or Lease Name Brunner Pan American AFK
3. Address of Operator 105 South 4th St., Artesia, NM 88210	9. Well No. State 1
4. Location of Well UNIT LETTER 0, 330 FEET FROM THE South LINE AND 2310 FEET FROM THE East LINE, SECTION 9 TOWNSHIP 10S RANGE 27E NMPM.	10. Field and Pool, or Wildcat Und. Diablo SA
15. Elevation (Show whether DF, RT, GR, etc.) 3866.5' GR	12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 2203'. Plugged well as follows:
Circulate hole with 10# mud.
Spot 30 sx cement plug from 1542-1442'.
Spot 35 sx cement plug from 1010-910'.
Spot 50 sx cement plug from 510-410'. Wait 2 hrs, tagged plug at 400'.
Set 50 sx surface plug.
Installed dry hole marker.
Plugging completed 8-19-88.

Verbal permission for plugging given by Mike Williams, NMOCD, Artesia, NM
7-11-88.

Post ID-2
9-2-88
P&A

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed Jesus Anita S. Soderstrom TITLE Production Supervisor DATE 8-22-88

APPROVED BY Johnny Robinson TITLE INSPECTOR DATE 2-28-91

CONDITIONS OF APPROVAL, IF ANY:

OK GW