STATE OF NEW MEXICO NERGY AND MINERALS DEPARTMENT

ENERGY AND MINERALS DEPARTMENT	
OIL CONSERVATION DIVISION	Form C-103 ·
DISTRIBUTION P. O. BOX 208 RECEIVED	Revised 10-1-78
SANTA FE, NEW MEXICO 87501	•
FILE	Sa, Indicate Type of Lease
U.S.G.S.	State X Fee
LAND OFFICE	5. State Oil & Gas Lease No.
GPERATOR V	LG 939
O.C. D.	- manning
SUNDRY NOTICES AND PEPORTS ON WELL STEEL OFFICE	
SUNDRY NOTICES AND REPORTS ON WELL STEEL OFFICE (DO NOT USE THIS FORM FOR PROPOSALS TO BRILL OR TO DECEMEN OR PLUG BACK TO A DIFFER HY RESERVOIR.	
USE "APPLICATION FOR PERMIT (FORM C-101) FOR JULY PROPERTY	7. Unit Agreement Name
OIL GAB WELL X OYHER-	8. Farm or Lease Name
2. Name of Operator	
Yates Petroleum Corporation	Witz VN State
1. Address of Operator	9. Well No.
- 	3
105 South 4th St., Artesia, NM 88210	10. Field and Poul, or Wildcat
4. Location of Well	Wildcat Penn
UNIT LETYER I 1980 FEET FROM THE SOUTH LINE AND 660 FEET F	WOW MITGGET LEITH
THE East LINE, SECTION 26 TOWNSHIP 9S RANGE 26E	
THELINE, SECTION TOWNSHIP RANGE	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3806.5' GR	Chaves
3806.5 GK	Chaves
Check Appropriate Box To Indicate Nature of Notice, Report or	Other Data
SUBSECTION OF SU	FNT REPORT OF:
NOTICE OF INTENTION TO: SUBSEQUE	ENT REPORT OF:
NOTICE OF INTERVIOR FOR	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK COMMENCE DHILLING OPHS.	ALTERING CASING PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS.	ALTERING CASING PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK COMMENCE DHILLING OPNS.	ALTERING CASING PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CABING CHANGE PLANS CASING TEST AND CEMENT JQB	ALTERING CASING PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CABING CHANGE PLANS CASING TEST AND CEMENT JQB	ALTERING CASING PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. X PULL OR ALTER CASING CHANGE PLANS OTHER OTHER	ALTERING CASING PLUG AND ABANDONMENT
PLUG AND ABANDON REMEDIAL WORK COMMENCE DHILLING OPNS. X TEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JQS X OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclu-	ALTERING CASING PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusively) SEE RULE 1103.	ALTERING CASING PLUG AND ABAHDOHMENT ding estimated date of starting any proposed
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusions) SEE RULE 1703. Spudded 12-1/4" hole at 5:30 PM 6-11-88. Ran 25 jts 8-5/8" 24# J-	ALTERING CASING PLUG AND ABANDONMENT ding estimated date of starting any proposed -55 ST&C casing set
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusions) SEE RULE 1703. Spudded 12-1/4" hole at 5:30 PM 6-11-88. Ran 25 jts 8-5/8" 24# J-	ALTERING CASING PLUG AND ABANDONMENT ding estimated date of starting any proposed -55 ST&C casing set
PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. TEMPORARILY ABANDON CHANGE PLANS CASINE TEST AND CEMENT JQB X OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusions) SEE RULE 1703. Spudded 12-1/4" hole at 5:30 PM 6-11-88. Ran 25 jts 8-5/8" 24# J-1083'. Texas Pattern notched guide shoe set 1083', insert float seement seeme	ALTERING CASING PLUG AND ABANDONMENT ding estimated date of starting any proposed -55 ST&C casing set set 1040'. Cemented
PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. TEMPORARILY ABANDON CHANGE PLANS CASINE TEST AND CEMENT JQB X OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusions) see Rule 1703. Spudded 12-1/4" hole at 5:30 PM 6-11-88. Ran 25 jts 8-5/8" 24# J-1083'. Texas Pattern notched guide shoe set 1083', insert float second s	ALTERING CASING PLUG AND ABANDONMENT ding estimated date of starting any proposed -55 ST&C casing set set 1040'. Cemented weight 12.8). Tailed
PLUG AND ABANDON TEMPORARILY ABANDON PULL OR ALTER CABING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusions) SEE RULE 1703. Spudded 12-1/4" hole at 5:30 PM 6-11-88. Ran 25 jts 8-5/8" 24# J-1083'. Texas Pattern notched guide shoe set 1083', insert float sw/375 sx Halliburton Lite w/1/2# Flocele and 3% CaCl2 (yield 1.84, in w/150 sx Class "C" with 2% CaCl2 (yield 1.32, weight 14.8). PE	ALTERING CASING PLUG AND ABANDONMENT ding estimated date of starting any proposed -55 ST&C casing set set 1040'. Cemented , weight 12.8). Tailed 0 3:30 AM 6-13-88. Bumped
PLUG AND ABANDON TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusions) SER RULE 1703. Spudded 12-1/4" hole at 5:30 PM 6-11-88. Ran 25 jts 8-5/8" 24# J-1083'. Texas Pattern notched guide shoe set 1083', insert float set w/375 sx Halliburton Lite w/1/2# Flocele and 3% CaCl2 (yield 1.84, in w/150 sx Class "C" with 2% CaCl2 (yield 1.32, weight 14.8). Purplug to 500 psi, released pressure and float held okay. Cement circ	ding estimated date of starting any proposed -55 ST&C casing set set 1040'. Cemented weight 12.8). Tailed 0 3:30 AM 6-13-88. Bumped reculated 25 sacks. WOC.
PLUG AND ABANDON TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusions) SER RULE 1703. Spudded 12-1/4" hole at 5:30 PM 6-11-88. Ran 25 jts 8-5/8" 24# J-1083'. Texas Pattern notched guide shoe set 1083', insert float set w/375 sx Halliburton Lite w/1/2# Flocele and 3% CaCl2 (yield 1.84, in w/150 sx Class "C" with 2% CaCl2 (yield 1.32, weight 14.8). Purplug to 500 psi, released pressure and float held okay. Cement circ	ding estimated date of starting any proposed -55 ST&C casing set set 1040'. Cemented weight 12.8). Tailed 0 3:30 AM 6-13-88. Bumped reculated 25 sacks. WOC.
PLUG AND ABANDON TEMPORARILY ABANDON PULL OR ALTER CABING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusions) see Rule 1703. Spudded 12-1/4" hole at 5:30 PM 6-11-88. Ran 25 jts 8-5/8" 24# J-1083'. Texas Pattern notched guide shoe set 1083', insert float sw/375 sx Halliburton Lite w/1/2# Flocele and 3% CaC12 (yield 1.84, in w/150 sx Class "C" with 2% CaC12 (yield 1.32, weight 14.8). Puplug to 500 psi, released pressure and float held okay. Cement cire Drilled out 11:00 PM 6-13-88. WOC 19 hrs and 30 minutes. NU and	ALTERING CASING PLUE AND ABANDONMENT ding estimated date of starting any proposed -55 ST&C casing set set 1040'. Cemented , weight 12.8). Tailed 0 3:30 AM 6-13-88. Bumped coulated 25 sacks. WOC. tested blind rams and
PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. TEMPORABILY ABANDON PULL OR ALTER CASING OTHER TO THER TO TH	ALTERING CASING PLUE AND ABANDONMENT ding estimated date of starting any proposed -55 ST&C casing set set 1040'. Cemented , weight 12.8). Tailed 0 3:30 AM 6-13-88. Bumped coulated 25 sacks. WOC. tested blind rams and
PLUG AND ABANDON TEMPORARILY ABANDON PULL OR ALTER CABING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusions) see Rule 1703. Spudded 12-1/4" hole at 5:30 PM 6-11-88. Ran 25 jts 8-5/8" 24# J-1083'. Texas Pattern notched guide shoe set 1083', insert float sw/375 sx Halliburton Lite w/1/2# Flocele and 3% CaC12 (yield 1.84, in w/150 sx Class "C" with 2% CaC12 (yield 1.32, weight 14.8). Puplug to 500 psi, released pressure and float held okay. Cement cire Drilled out 11:00 PM 6-13-88. WOC 19 hrs and 30 minutes. NU and	ALTERING CASING PLUE AND ABANDONMENT ding estimated date of starting any proposed -55 ST&C casing set set 1040'. Cemented , weight 12.8). Tailed 0 3:30 AM 6-13-88. Bumped coulated 25 sacks. WOC. tested blind rams and
PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. TEMPORABILY ABANDON PULL OR ALTER CASING OTHER TO THER TO TH	ALTERING CASING PLUE AND ABANDONMENT ding estimated date of starting any proposed -55 ST&C casing set set 1040'. Cemented , weight 12.8). Tailed 0 3:30 AM 6-13-88. Bumped coulated 25 sacks. WOC. tested blind rams and
PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. TEMPORABILY ABANDON PULL OR ALTER CASING OTHER TO THER TO TH	ALTERING CASING PLUE AND ABANDONMENT ding estimated date of starting any proposed -55 ST&C casing set set 1040'. Cemented , weight 12.8). Tailed 0 3:30 AM 6-13-88. Bumped coulated 25 sacks. WOC. tested blind rams and
PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. TEMPORABILY ABANDON PULL OR ALTER CASING OTHER TO THER TO TH	ALTERING CASING PLUE AND ABANDONMENT ding estimated date of starting any proposed -55 ST&C casing set set 1040'. Cemented , weight 12.8). Tailed 0 3:30 AM 6-13-88. Bumped coulated 25 sacks. WOC. tested blind rams and
PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. TEMPORABILY ABANDON PULL OR ALTER CASING OTHER TO THER TO TH	ALTERING CASING PLUE AND ABANDONMENT ding estimated date of starting any proposed -55 ST&C casing set set 1040'. Cemented , weight 12.8). Tailed 0 3:30 AM 6-13-88. Bumped coulated 25 sacks. WOC. tested blind rams and
PLUG AND ABANDON PULL OR ALTER CABING TEMPORABILY ABANDON PULL OR ALTER CABING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusively) see Rule 1703. Spudded 12-1/4" hole at 5:30 PM 6-11-88. Ran 25 jts 8-5/8" 24# J-1083'. Texas Pattern notched guide shoe set 1083', insert float sw/375 sx Halliburton Lite w/1/2# Flocele and 3% CaCl2 (yield 1.84, in w/150 sx Class "C" with 2% CaCl2 (yield 1.32, weight 14.8). Proplug to 500 psi, released pressure and float held okay. Cement cir Drilled out 11:00 PM 6-13-88. WOC 19 hrs and 30 minutes. NU and pipe rams to 1000 psi for 30 minutes, OK. Reduced hole to 7-7/8".	ALTERING CASING PLUE AND ABANDONMENT ding estimated date of starting any proposed -55 ST&C casing set set 1040'. Cemented , weight 12.8). Tailed 0 3:30 AM 6-13-88. Bumped coulated 25 sacks. WOC. tested blind rams and
PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. TEMPORABILY ABANDON PULL OR ALTER CASING OTHER TO THER TO TH	ALTERING CASING PLUE AND ABANDONMENT ding estimated date of starting any proposed -55 ST&C casing set set 1040'. Cemented , weight 12.8). Tailed 0 3:30 AM 6-13-88. Bumped coulated 25 sacks. WOC. tested blind rams and

18. I hereby certify that th	ne information above is true and complete	e to the best of my knowledge and belief.		
helest asi	To Dogler	Production Supervisor	DATE_	6-14-88
APPROVED BY	Original Signed By Mike Williams	TITLE	DATE_	SEP 1 2 1988