· ·	÷		•	4		
Submit 3 Copies to Appropriate District Office	State of N Energy, Minerals and Nat			j.	Form C-10 Revised 1-1	17.1
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION 310 Old Santa Fe Trail, Room 206			WELL API NO.	-205-626	29
DISTRICT II P.O. Drawer DD, Anesia, NM 88210 Santa Fe, New Mexico 87503				5. Indicate Type		FEE KX
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410				6. State Oil & G		FEE 6.4
SUNDRY NOTIC	CES AND REPORTS OF	WEI	15			
(DO NOT USE THIS FORM FOR PROF DIFFERENT RESERV		EEPEN (OR PLUG BACK TO A	7. Lease Name of	or Unit Agreement Name	
1. Type of Well:		<u>.</u>		- Whitney		
OL GAS WELL	OTHER					· .
2. Name of Operator	_			8. Well No.	" 0	
Yates Exploration Comp 3. Address of Operator	bany, Inc.		<u>,</u>	9. Pool name or	#3 Wildcat	
P.O. Box 1608, Albuque	ergue. NM 87103-1	608		1	undesignated)	76:10
4. Well Location	<u>e. que, ini 0/100 1</u>	000				<u>+</u>
Unit Letter : :	Feet From The Sou	ıth	Line and231	0 Feet Fro	m The <u>East</u>	Line
Sertion 34	Townshin 10S	-	275	chause		
Section ³⁴		Rai whether	nge 27E DF, RKB, RT, GR, etc.)	NMPM Chave	es ////////////////////////////////////	County
			4.4 GL			
11. Check A	ppropriate Box to Ind	icate N	Nature of Notice, R	leport, or Othe	r Data	
		(BSEQUENT	REPORTOF	
NOTICE OF INTE	ENTION TO:		300			
		N				
— ––	ENTION TO: PLUG AND ABANDON	X	REMEDIAL WORK		ALTERING CASING	
	PLUG AND ABANDON		REMEDIAL WORK	3 OPNS.	ALTERING CASING	
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK	3 OPNS.	ALTERING CASING	
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS		REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER:		ALTERING CASING PLUG AND ABANDON	[]
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS		REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER:	GOPNS.	ALTERING CASING PLUG AND ABANDON PLUG AND ABANDON	
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS	details, a	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: nd give pertinent dates, inc	GOPNS.	ALTERING CASING PLUG AND ABANDON	
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS ons (Clearly state all pertinent of follows : rom TD to 1990 to	details, a	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: nd give pertinent dates, inc	GOPNS.	ALTERING CASING PLUG AND ABANDON PLUG AND ABANDON	
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS ons (Clearly state all pertinent of follows: rom TD to 1990 to with mud laden fl top of San Andre	details, a cove luid.	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: not give pertiment dates, income r Slaughter.	GOPNS.	ALTERING CASING PLUG AND ABANDON te of starting any proposed CONCERNESS FEB - 6 1395	
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS ons (Clearly state all pertinent of follows: rom TD to 1990 to with mud laden fl top of San Andre	details, a cove luid.	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: not give pertiment dates, income r Slaughter.	GOPNS.	ALTERING CASING PLUG AND ABANDON te of starting any proposed CONCERNESS FEB - 6 1395	
PERFORM REMEDIAL WORK Image: Complete Completed Operation work) PULL OR ALTER CASING Image: Completed Operation work) DTHER: Image: Completed Operation work) 12. Describe Proposed or Completed Operation work) SEE RULE 1103. Propose to plug well as Set 25 sak plug fr Tag and fill hole Set 25 sak plug at Set	PLUG AND ABANDON CHANGE PLANS ons (Clearly state all pertinent of follows: rom TD to 1990 to with mud laden fl top of San Andre top of Queen fro o cover base of su	cove luid. es fr om 70 urfac	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: not give pertiment dates, inco r Slaughter. om 1400' to 150 0' to 800'. e casing from 1	GOPNS.	ALTERING CASING PLUG AND ABANDOR te of starting any proposed COCOMPANY FEB - 6 (295	
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS ons (Clearly state all pertinent of follows: rom TD to 1990 to with mud laden fl top of San Andre top of Queen fro o cover base of su	cove luid. es fr om 70 urfac	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: not give pertiment dates, inco r Slaughter. om 1400' to 150 0' to 800'. e casing from 1	GOPNS.	ALTERING CASING PLUG AND ABANDON te of starting any proposed CONCERNESS FEB - 6 1395	
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS ons (Clearly state all pertinent of follows: rom TD to 1990 to with mud laden fl top of San Andre top of Queen fro o cover base of su	cove luid. es fr om 70 urfac	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: not give pertiment dates, inco r Slaughter. om 1400' to 150 0' to 800'. e casing from 1	GOPNS.	ALTERING CASING PLUG AND ABANDOR te of starting any proposed COCOMPANY FEB - 6 (295	
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS ons (Clearly state all pertinent of follows: rom TD to 1990 to with mud laden fl top of San Andre top of Queen fro o cover base of su	cove luid. es fr om 70 urfac	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: not give pertiment dates, inco r Slaughter. om 1400' to 150 0' to 800'. e casing from 1	GOPNS.	ALTERING CASING PLUG AND ABANDOR te of starting any proposed COCOMPANY FEB - 6 (295	
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS ons (Clearly state all pertinent of follows: rom TD to 1990 to with mud laden fl top of San Andre top of Queen fro o cover base of su	cove luid. es fr om 70 urfac	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: not give pertiment dates, inco r Slaughter. om 1400' to 150 0' to 800'. e casing from 1	GOPNS.	ALTERING CASING PLUG AND ABANDOR te of starting any proposed COCOMPANY FEB - 6 (295	
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS ons (Clearly state all pertinent of follows: rom TD to 1990 to with mud laden fl top of San Andre top of Queen fro o cover base of su	cove luid. es fr om 70 urfac	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: not give pertiment dates, inco r Slaughter. om 1400' to 150 0' to 800'. e casing from 1	GOPNS.	ALTERING CASING PLUG AND ABANDOR te of starting any proposed COCOMPANY FEB - 6 (295	
PERFORM REMEDIAL WORK Image: Composed of Completed Operation work) DULL OR ALTER CASING Image: Completed Operation work) DTHER: Image: Completed Operation work) SEE RULE 1103. Propose to plug well as Set 25 sak plug fr Tag and fill hole Set 25 sak plug at Set 10 sak plug at Set 25 sak plug at Set 10 sak plug at Set 25 sak plug at S	PLUG AND ABANDON CHANGE PLANS ons (Clearly state all pertinent of 5 follows: rom TD to 1990 to with mud laden fl top of San Andre top of Queen fro top of Queen fro top of Queen fro top of Queen fro	cove luid. 25 fr 0m 70 urfac	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: Ind give pertiment dates, income r Slaughter. om 1400' to 150 0' to 800'. e casing from 1 y hole marker.	GOPNS.	ALTERING CASING PLUG AND ABANDOR te of starting any proposed COCOMPANY FEB - 6 (295	
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS ons (Clearly state all pertinent of 5 follows: rom TD to 1990 to with mud laden fl top of San Andre top of Queen fro top of Queen fro top of Queen fro top of Queen fro	details, a cove luid. es fr om 70 urfac l1 dr	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: of give pertiment dates, income r Slaughter. om 1400' to 150 0' to 800'. e casing from 1 y hole marker.	GOPNS.	ALTERING CASING PLUG AND ABANDON the of starting any proposed FEB - 6 (395))
PERFORM REMEDIAL WORK Image: Composed of Completed Operation work) DULL OR ALTER CASING Image: Completed Operation work) DTHER: Image: Completed Operation work) SEE RULE 1103. Propose to plug well as Set 25 sak plug fr Tag and fill hole Set 25 sak plug at Set 10 sak plug at Set 25 sak plug at Set 10 sak plug at Set 25 sak plug at S	PLUG AND ABANDON CHANGE PLANS ons (Clearly state all pertinent of 5 follows: rom TD to 1990 to with mud laden fl top of San Andre top of Queen fro top of Queen fro top of Queen fro top of Queen fro	details, a cove luid. es fr om 70 urfac l1 dr	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: Ind give pertiment dates, income r Slaughter. om 1400' to 150 0' to 800'. e casing from 1 y hole marker.	GOPNS.	ALTERING CASING PLUG AND ABANDOR te of starting any proposed COCOMPANY FEB - 6 (295)
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS ons (Clearly state all pertinent of follows: rom TD to 1990 to with mud laden fl top of San Andre top of Queen fro top of Queen fro top of Queen fro top of San Andre top of San Andre	details, a cove luid. es fr om 70 urfac l1 dr	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: of give pertiment dates, income r Slaughter. om 1400' to 150 0' to 800'. e casing from 1 y hole marker.	GOPNS.	ALTERING CASING PLUG AND ABANDON the of starting any proposed FEB - 6 (395))
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS ons (Clearly state all pertinent of follows: rom TD to 1990 to with mud laden fl top of San Andre top of Queen fro top of Queen f	details, a cove luid. es fr om 70 urfac l1 dr	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: of give pertiment dates, income r Slaughter. om 1400' to 150 0' to 800'. e casing from 1 y hole marker.	GOPNS.	ALTERING CASING PLUG AND ABANDON te of starting any proposed FEB - 6 1395 . CASING, SAR DATE 1/31/95)
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS ons (Clearly state all pertinent of follows: rom TD to 1990 to with mud laden fl top of San Andre top of Queen fro top of Queen f	details, a details, a cove luid. es fr om 70 urfac l1 dr	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: of give pertiment dates, inc r Slaughter. om 1400' to 150 0' to 800'. e casing from 1 y hole marker. tet. tet. tet. tet. tet.	GOPNS.	ALTERING CASING PLUG AND ABANDON te of starting any proposed FEB - 6 (395 	D V.
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS ons (Clearly state all pertinent of follows: rom TD to 1990 to with mud laden fl top of San Andre top of Queen fro top of Queen f	details, a cove luid. es fr om 70 urfac l1 dr	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: of give pertiment dates, inc r Slaughter. om 1400' to 150 0' to 800'. e casing from 1 y hole marker. tet. tet. tet. tet. tet.	GOPNS.	ALTERING CASING PLUG AND ABANDON te of starting any proposed FES - 6 (395 '. C.C.Y., SA FES - 7 (3	D V.