## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

THOT AND WINKLINGS TO	-1 711	1 (111)
NO. OF COPIED MELETYED		
DISTRIBUTION		
SANTA FE	V	
FILE	10	1
U.S.O.S.	_[	
LAND OFFICE	_	<u>/_</u>
OPERATOR	1	<u> </u>

## RECEIVED OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103 - Revised 10-1-78

DISTRIBUTION			VC413Cd 10.1 10
SANTA FE	SANTA FE, NEW MEXI	CQ187891 20	,
FILE V		MON TO OO	Sa. Indicate Type of Lease
U.S.O.S.			State X Fee
LAND OFFICE		O. C. D.	5, State Oil & Gas Leaso No.
OPERATOR V		artesia, Office	LG 5246
SUNDRY NO HOT USE THIS FORM FOR PROPOSI	NOTICES AND REPORTS ON WELLS TO DRILL ON TO DEEPEN OF PLUG BACK TO A	DIFFERENT NESERVOIR. ALS.)	
1.			7. Unit Agreement Name
OIL X WELL .	OTHER.		
2. Name of Operator			8, Farm or Lease Name
Yates Petroleum Corporation		Pathfinder AFT State	
		9. Well No.	
3. Address of Operator		3	
105 South 4th St., Artesia, NM 88210		10. Field and Pool, or Wildcat	
4. Location of Well	•	222	Wildcat
к 1650	FEET FROM THE South LINE	AND 2310 FEET FROM	
West the section	2003/ TOWNSHIP 105 M	ANGE 27E NMPM.	
THE LINE, SECTION _			<del></del>
THIMITITE TO THE TOTAL THE TOTAL TO THE TOTAL TO THE TOTAL TO THE TOTAL THE THE TOTAL THE TOTAL THE TOTAL THE TOTAL THE TOTAL THE TOTAL THE THE TOTAL THE TOTAL THE TOTAL THE TOTAL THE TOTAL THE TOTAL THE THE TOTAL	15. Elevation (Show whether DF, RT,	, GR, eic.)	12. County
3839.5' GR		Chaves	
16. Check An	propriate Box To Indicate Nature	of Notice, Report or Ot	her Data
NOTICE OF INT		SUBSEQUEN.	T REPORT OF:
NOTICE OF INT			,
رت	PLUG AND ABANDON REMED	DIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK	l l	ENCE ONILLING OPNS.	PLUG AND ABANDONMENT
TEMPORARILY ABANDON	r)	G TEST AND CEMENT JOB	
PULL OR ALTER CASING	CHANGE PLANS CASING	HER Drilling status	XX
	رته اس	HER DITTITIE OFGER	
OTHER			
		1 in postingue datas includio	estimated date of starting any proposed
17. Describe Proposed or Completed Open	itions (Clearly state all pertinent details, and	Rice heitenent autes, the manif	• • • • •
work) SEE RULE 1103.			

11-4-88. Moved in rotary rig and continue to drill to a new total depth of 7200' and

test the Fusselman formation. Drilled rat and mouse holes. Picked up drill collars and drill pipe. Reamed and circulated to bottom. Resumed drilling.

11-14-88. TD 4443'.

Original Signed Rev		
Original Signed By  WEY 1 3 1980	18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  Production Supervisor	DATE 11-15-88
TITLE DATE	Original Signed By weet More Office (Williams	NOV 1 3 1988