					C
Submit 3 Copies To Appropriate District Office	State of Nev				Form C-103
District I	Energy, Minerals and	l Natur	ral Resources	WELL ADINO	Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240 District II OH. CONSERNATION DIVISION			WELL API NO. 30-005-62636		
811 South First, Artesia, NM 88210 OIL CONSERVATION DIVISION			5. Indicate Type (of Lease	
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410			· · · · · · -	X FEE	
District IV 1220 S. St. Francis Dr., Santa Fe, NM Santa Fe, NM 87505			6. State Oil & G		
87505				LG-5246	
	CES AND REPORTS ON W		IC PACK TO A	7. Lease Name or	Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR \$\frac{1}{2}\$			R SUCH	D 11 5 1	
PROPOSALS.)				Pathfinder AFT State	
1. Type of Well: Oil Well Gas Well X	Other	,	167		
2. Name of Operator	Other	ادر	10 A 30	8. Well No.	
Yates Petroleum Corpoi	ration /	CASO	(B) 5)	3	
3. Address of Operator	5	**************************************	Va 3	9. Pool name or	Wildcat
105 S. 4th Street Artesi	a, NM 88210 💢	7/2/	180		Diablo Wolfcamp
	\chi_0,		0/4 60/	Gas	
4. Well Location	16	9>~	77.1.36		
Unit Letter K: 1650 feet from the South line and 2310 feet from the West line					
Omit Letter N. 1630	reet from the SOUII	<u>+ 11</u>	ne and <u>∠310</u>	reet from the	<u>est</u> line
Section 21	Township 10S I	Range	27E	NMPM Cho	aves County
	10. Elevation (Show wheth			.)	aves county
光光连续型,逐步运 车中10年的操作		3840'			
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF IN	TENTION TO:		SUB	SEQUENT REI	PORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	7	REMEDIAL WORK		ALTERING
					CASING
TEMPORARILY ABANDON	CHANGE PLANS]	COMMENCE DRI	LLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION	7	CASING TEST AN CEMENT JOB	ND	
OTHER:					
	erations (Clearly state all no	ertinon	OTHER: Perforate		X
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.					
Released packer and POOH.	Circulate hole clean. S	et CIB	BP at 6250'. Cap	with 10' cemer	nt. Perforate 6196'-
6202' (6 SPF – 42 holes) and 6228'-6236' (6 SPF – 30 holes). Spotted 50 gals 7-1/2% IC acid. Acidize with 1200					
gals 7-1/2% IC acid and 108 balls. Set CIBP at 6134' with 10' cement. Perforate Cisco 6044'-6062' (2 SFP – 38 holes), 6072'-6086' (2 SPF – 30 holes) and 6097'-6108' (2 SPF – 24 holes). Spotted 100 gals of 15% IC acid.					
Acidize with 2500 gals 15% IC acid and 138 balls. Set CIBP at 6000' with 35' cement. Perforate Wolfcamp					
5512'-5536' (2 SPF – 50 holes). TIH with packer and tubing to 5400'. Acidize with 1200 gals of 15% IC acid and 75					
balls.	·	J		9	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNATURE Jim & Hunta TITLE Regulatory Compliance Supervisor DATE August 12, 2002					
Type or print name Ting Huerl	a			Telenhone N	o. 505-748-1471
(This space for State use)				rerephone 14	****
(Ab)	. 121/				AUG 21 2002
APPPROVED BY <u>locand</u> Conditions of approval, if any:	Chy JUY TIT	TLE			DATE