

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Artesia, NM 88210

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM 38342 27916

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

N/A

7. UNIT AGREEMENT NAME

N/A

8. FARM OR LEASE NAME

Helen Collins Fed. Com.

9. WELL NO.

7 1

10. FIELD AND POOL, OR WILDCAT

Pecos Slope Abo.

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 4, 7S, R26E

12. COUNTY OR PARISH

Chaves

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

SEP 21 '88

O.C.D.
ARTESIA OFFICE

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Stevens Operating Corporation

3. ADDRESS OF OPERATOR

P.O. Box 2203, Roswell, New Mexico 88202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

660 FNL 1980 FEL, Sec. 4, T7S, R26E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3650.2 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANT

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other) Spud and Casing

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

August 31, 1988

Spud well w/12 1/4" bit 10:00 AM 8/31/88. Ran 19 jts. 8 5/8", 24 # csg. set @ 746'. Cmt. w/200 sxs halite + 225 sxs "c" cmt. Plug down @ 4:30 AM, circulated 50 sxs. WOC 18 hrs. Pressure up 1000 # for 30 minutes logging no pressure decrease.

Sept. 8, 1988

TD 4400' 11:30 AM Sept. 8, 1988.

Sept. 9, 1988

Ran 104 jts. 4 1/2", 11.6 # csg. + 10' shoe jt. @ 4400'. Cmt. w/500 sxs. 35/65 POZ. Cmt. plug down @ 11:59 AM, Sept. 9, 1988. WOC 18 hrs. Pressure up 1000 # for 30 minutes logging no pressure decrease.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE General Manager

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

DATE Sept. 14, 1988

ACCEPTED FOR RECORD
PETER W. CHESTER

DATE

SEP 19 1988

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

*See Instructions on Reverse Side