

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-005-62659
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	LG-4928
7. Lease Name or Unit Agreement Name	Dragonfly ARY State
8. Well No.	1
9. Pool name or Wildcat	Foor Ranch San Andres

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	RECEIVED OCD - ARTESIA
2. Name of Operator YATES PETROLEUM CORPORATION	
3. Address of Operator 105 South 4th St., Artesia, NM 88210	
4. Well Location Unit Letter <u>0</u> : <u>660</u> Feet From The <u>South</u> Line and <u>1650</u> Feet From The <u>East</u> Line Section <u>31</u> Township <u>9S</u> Range <u>27E</u> NMPM Chaves County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3916' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

Post IF-2
3-13-98
PvH

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-24-98 - Moved in and rigged up pulling unit. POOH with rods and pump. Nippled down wellhead. Nippled up BOP. POOH with tubing. Shut well in.
2-25-98 - RIH with 2-7/8" tubing and tagged top of cement at 6145'. NOTE: CIBP set at 6180' and capped with 35' of cement. Circulated hole with mud laden fluid. POOH with tubing. Spotted a 25 sack Class C cement at 5050'. POOH with tubing 20 stands. Shut well in.
2-26-98 - RIH with tubing and tagged top of cement at 4827'. POOH with tubing. Spotted 25 sacks Class "C" cement with 2% CaCl2 at 2050'. POOH with tubing. WOC. RIH with tubing and tagged top of cement at 1848'. POOH with tubing. Spotted 25 sacks Class C cement with 2% CaCl2 at 605'. POOH with tubing. WOC. RIH with tubing and tagged top of cement at 375'. POOH with tubing. Spotted 10 sacks Class C cement at surface. Rigged down pulling unit. Cleaned location. Installed regulation abandonment marker. PLUGGED AND ABANDONED - FINAL REPORT. Plugging completed 2-25-98.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Operations Technician DATE Feb. 27, 1998
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY [Signature] TITLE FED Rep I DATE 7-28-98
CONDITIONS OF APPROVAL, IF ANY: