

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

NM Oil Cons. Commission  
Drawer DD  
Artesia, NM 88210

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

BHP Petroleum (Americas) Inc.

3. Address and Telephone No.

(713) 961-8423

1360 Post Oak Blvd., Suite 500, Houston, Texas 77056-3020

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

NE/NE Section 8, T11S, R27E, NMPM

5. Lease Designation and Serial No.

NM02146

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Conoco "8" Federal 1

9. API Well No.

30-005-62674

10. Field and Pool, or Exploratory Area

Comanche Springs/Pre-Perm

11. County or Parish, State

Chaves, New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other

- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- 1.) Set CIBP @ 6,150'.  
2.) Test CIBP and casing to 500 psi.  
3.) Spot 10 sx cmt. on CIBP and load hole w/9.5 ppg mud laden fluid.  
4.) Set a 25 sx plug from 2,300' - 2,450'.  
5.) Set a 25 sx plug from 1,100' - 1,250'.  
6.) Set a 10 sx surface plug from 3' - ~~25~~ 53'.  
7.) Cut off wellhead 3' below ground level and weld on a steel plate and P & A marker.  
8.) Clean location and restore to pre-move condition.

14. I hereby certify that the foregoing is true and correct

Signed

*Carl Kolbe*

Title

Regulatory Affairs Coordinator

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

Date

DEC 14 1994

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*See Instruction on Reverse Side