Submit 3 Copies To Appropriate District Office District I	State of New Mexico Energy, Minerals and Natural Resources		W Sp	Form C-103 Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
<u>District II</u> 811 South First, Artesia, NM 88210	OIL CONSERVATION DIVISION		30-005-62746	
District III	1220 South St. Francis Dr.		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		STATE X FEE 6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM			LG-5230	
67505				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			/. Lease Name or	Unit Agreement Name:
DIFFERENT RESERVOIR. USE "APPLIC.			Carable Davillare	
PROPOSALS.)		14120	South Dallas	
1. Type of Well:	~. ¬	91011121375X		
Oil Well Gas Well X	Other		70 111 11 11	
2. Name of Operator	ration / W		8. Well No.	
Yates Petroleum Corpor	ralion , w	20.000 220	9: Pool name or	Wildoot
3. Address of Operator	:- NIA 00010	0 65/000		
105 S. 4 th Street Artesi	ia, NM 88210	49750	Foor Ranch W	oircamp Gas
4. Well Location	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	- SA		
4. Well Location				
Unit Letter B: 660 feet from the North line and 7.400 feet from the East line				
The Letter B . 600 leet from the TYOTH line that Tyou leet from the Least				
Section 2	Township 10S Range	26E N	мрм Chav	es County
	10. Elevation (Show whether D.			Later a levy skill to the visit of the second
3864' GR				
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
				ALTERING
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	K ∐	CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	LLING OPNS.	PLUG AND
	MULTIPLE	CASING TEST AN	ND	ABANDONMENT
PULL OR ALTER CASING	COMPLETION	CEMENT JOB		
OTHER:		OTHER: Recomp		X
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of				
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or				
recompilation.				
10 (00 (00 - N)) and a discretization and a product and a				
10/23/02 - Nippled up BOP. Unset packer and POOH.				
10/24/02 – TIH with 4-3/4" bit and scraper. Tagged tight spot at 2500'. Worked scraper through spot. Ran bit				
down to 5900'. Circulated hole with 2% KCL. POOH with bit and scraper. 10/25-27/02 – Set CIBP at 5870'. Capped with 35' cement. Perforate Wolfcamp 5286'-5292' (2 SPF) with 54				
		. Periorate Wolfd	camp 5286"-5292	(2 SPF) WITH 54
holes, 5362'-5378' (2 SPF) with 34 holes.				
10/29/02 – Acidize Lower Wolfcamp 5362'-5378' with 2000 gals 20% IC acid and 50 balls. 11/1/02 – Acidize Upper Wolfcamp 5266'-5292' with 2600 gals 20% IC acid and 81 balls.				
11/6/02 – Acidize apper Walicamp 3288-3272 Will 2800 gais 20% ic acid and 81 balls. 11/6/02 – TIH with Baker Loc Set packer and 1.87" on/off tool set at 5218'.				
THOUSE THE WHIT BURGE ESS SOT PUBLICATION STRUCTURE OF ST				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE				
Tion I benefit				
Type or print name Ting Huer	 		Telephone No	o. 505-748-1471
	ORIGINAL SIGNED BY TIM W	GUM		MARY 4 SE MOOF
APPPROVED BY	DISTRICT II SUPERVISOR			MOV 1 9 2000 DATE
Conditions of approval, if any:	TITLE			_DVIR