

+clsr
dp

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED

1-18-93

O.C.D.

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240
DISTRICT II
P.O. Drawer DD, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-005-62751
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG 5246

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER RECOMPLETION
2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210

7. Lease Name or Unit Agreement Name Pathfinder AFT State
8. Well No. 6
9. Pool name or Wildcat Undes. Wolfcamp

4. Well Location Unit Letter <u>F</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>11980</u> Feet From The <u>West</u> Line Section <u>21</u> Township <u>10S</u> Range <u>27E</u> NMPM Chaves County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3852.5' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Plugback & test Wolfcamp <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-30-92. RU wireline. TIH w/gauge ring and junk basket to 6450'. TOH w/gauge ring and junk basket. Set CIBP at 6300' w/35' cement on top. Perforated 5573-5584' w/12 holes (1 SPF). Set packer at 5623'. Tested casing and CIBP to 2000 psi for 10 minutes, OK. Moved packer to 5500'. Swabbed well. Acidized perms 5573-5584' w/2000 gals 20% HCL/NEFE acid. Recovered load.

1-1-93. Well returned to production.

Post ID-2
2-26-93
PJA Friedman

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 1-18-93

TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

FEB 17 1993