State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION P.O. Box 2088

WELL API NO.

DISTRICT II Santa Fe New Mexico, 87504-2088	20-005-62769
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088	5. Indicate Type of Lease
DISTRICT III	STATE X FEE
1000 Rio Brazos Rd., Aziec, NM 87410	6. State Oil & Gas Lease No.
	LG 8007
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMECE!VED	7. Lease Name or Unit Agreement Name
(FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well:	Samedan "35" State
OIL GAS WELL OTHER Dry APR 11 '90	
2. Name of Operator	8. Well No.
BHP Petroleum (Americas) Inc.	2
3. Address of Operator	9. Pool name or Wildcat
5847 San Felipe Suite 3600 Houston TX 77057-3005	Rabbit Flats Pre-Permian
4. Well Location	(Extension)
Unit Letter : 1980Feet From The South Line and	660 Feet From The East Line
Section 35 Township 10-S Range 26-E	NMPM Chaves County
10. Elevation (Show whether DF, RKB, RT, GR, etc.	·
3673.3 GL	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRII	LING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING TEST AND CEMENT JOB	
CASING (EST AIR	D CEMENT JOB
OTHER: OTHER:	
12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, worsported RHLE 1193/4" hole on 2/13/90. Drld to 1350 of J-55 24# ST&C. Set @ 1207 KB. Cmt w/500 Floseal, 3 pps gilsonite, tail in w/200 sx "C sx to pits. Drl to 6170'. Ran DST #1 (Mor drlg break @ 6144-50', 6 mpf dn to 2 3/4 mpf 20 units to 44 units. Sample chamber recovery No liquid. On 2/27/90 reached TD 6692'. logs. Prepare to P&A. Set plugs as follow 6358'. Cmt w/35 sx neat "C". Plug #2 - 5310 neat "C". Plug #3 4596-4496'. Cmt w/35 sx 2398-2298'. Cmt w/35 sx neat "C". Plug #5 - sx. WOC 5 hrs. Tag plug #5 @ 967'. Set 10 off wellhead. Weld on P&A marker. Well P&A 3/1/90.	**Ran 27 jts 8 5/8" sx Howco Lite, 1/4# " w/2% CaCl ₂ . Circ 30 for 10-10-10-10-10-10-10-10-10-10-10-10-10-1
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	- 112
SIGNATURE Senior Petroleum Engr. DATE 3/12 /90	
Chris Camden	
TYPE OR PRINT NAME OTHERS GENERALLY	TELEPHONE NO.
(This space for State Use)	

TILE PR AND BAR INSPECTOR